

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33471
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	N/A
7. Lease Name or Unit Agreement Name	J.H. WILLIAMS "A"
8. Well No.	4
9. Pool name or Wildcat	MCKEE/ELLENBERGER OIL

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Amerada Hess Corporation
3. Address of Operator P.O. Box 2040, Houston, TX 77252-2040	4. Well Location Unit Letter <u>N</u> : <u>800</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>34</u> Township <u>19S</u> Range <u>37E</u> NMPM <u>LEA</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3561' GR.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☒  
OTHER: SETTING PRODUCTION CASING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

07-24-96: R.U. BULL ROGERS CSG. CREW AND RAN 39 JTS. OF 5-1/2", 17#, K-55, 8RL, SMLS, R3, "A" CSG., AND 131 JTS. OF 5-1/2", 17#, L80, 8RL, SMLS, R3, "A" CSG., SET @ 7,100', SHOE @ 7,098', F.C. @ 7,015', 80 TURBOLIZER AND 30 CENT. CEMENTED WITH DOWELL. PUMPED 100 BBLS. OF MUD WASH, MIXED AND PUMPED 600 SX. OF CLASS "C" CEMENT, 50:50 POZ. + 2% GEL. + 8#/SX. SALT + .4% D59 + 1/4#/SX. C.F. (14.1# 1.46). TAIL WITH 550 SX. OF CLASS "H" CEMENT, + 6#/SX. SALT + .3% D65 + .9% D59 + .2% D79 + .2% D46 + 1/4#/SX. C.F. (15.6# 1.26). DISPLACED WITH 163 BBLS. F. WATER @ 7 BBLS/MIN. FINAL CIRC. W/1900 PSI. BUMP PLUG W/2600 PSI @ 10:30 P.M. EST. TOP OF CMT. @ 2500'. CIRC. 50 BBLS. MUD WASH TO PIT. GOOD RETURNS THRU-OUT JOB.

07-25-96: NU KUAERNER NAT: KSB 11" 3M X 7-1/16" 3M TBG. HD. TEST W/3000 PSI. RELEASE RIG @ 3:00 A.M. TURNED OVER TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Jumper TITLE ADM. SUPERVISOR DRILLING DATE 07-30-96  
TYPE OR PRINT NAME MIKE JUMPER TELEPHONE NO. 713 609-4846

(This space for State Use)

APPROVED BY FIELD REP. II TITLE FIELD REP. II DATE 07-30-96  
CONDITIONS OF APPROVAL, IF ANY: