

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33568
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	NMB -1626
7. Lease Name or Unit Agreement Name	STATE "V"
8. Well No.	7
9. Pool name or Wildcat	EUMONT YATES SEVEN RIVERS
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3607 GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Amerada Hess Corporation
3. Address of Operator P.O. Box 2040, Houston, TX 77252-2040	4. Well Location Unit Letter B : 660 Feet From The NORTH Line and 1880 Feet From The EAST Line
Section 36 Township 19S Range 36E NMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3607 GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: RUNNING PRODUCTION CSG. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

09-19-96: R.U. BULL ROGERS CSG. CREW AND RUN 90 JTS. OF 5-1/2" 15.50#, K-55, 8RL, SMLS, R3, "A" CSG. SET AT 3,530', SHOE AT 3,528', FC AT 3,446', GAP SUB AT 3,248', AND RAN 20 TURBOLIZERS. CMT. WITH HOWCO. PUMP 400 SX. CLASS "C" HALLITITE + 5#/SX SALT + 1/4#/SX C.F. (12.6#, 1.99) TAIL WITH 200 SX CLASS "H" + 5#/SX CAL SEAL(16#, 1.17) DISPLACE WITH 82 BBLS. F. WATER AT 6 BBLS/MIN. FINAL CIRC. WITH 1100 PSI. BUMP PLUG WITH 1750 PSI AT 5:30 P.M. MST. GOOD RETURNS. STOP RECIPROCATING AFTER 37 BBLS. DISPLACED. LOST 5' FROM 3,535' TO 3,530'. CIRCULATE 35 SX. OF CMT TO PITS. TEST TUBING HEAD WITH 2250 PSI. O.K. RELEASED RIG AND TURNED OVER TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Jumper TITLE ADM. SUPERVISOR DRILLING DATE 09-20-96
TYPE OR PRINT NAME MIKE JUMPER TELEPHONE NO. 713- 609-4846

(This space for State Use)

SEP 30 1996

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: