

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-33919
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Bertha Barber
8. Well No. 16
9. Pool name or Wildcat Monument Abo

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Marathon Oil Company	
3. Address of Operator P.O. Box 2490 Hobbs, NM 88241	
4. Well Location Unit Letter K : 2140 Feet From The South Line and 1650 Feet From The West Line Section 5 Township 20-S Range 37-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) KB 3570' GL 3554'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Repair casing leak ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU pulling unit. POOH w/ rods & pump. ND wellhead & NU BOP. POOH w/ tbg.
TIH w/ 4-1/2" RBP & packer. Set RBP at 4920' and test w/ packer. POOH w/ packer.
TIH w/ 7" packer. Test liner hanger. PUH testing casing. After finding casing leak POOH.
TIH w/ cement retainer. Set above casing leak. Pump 150 sks cement. POOH w/ tbg.
TIH w/ bit. Drill cement retainer & cement. Test casing. POOH w/ bit.
TIH w/ retrieving tool for RBP. Latch RBP and release. POOH.
TIH w/ packer. Set above perms. Acidize Abo perms. Swab acid load back.
POOH w/ packer. TIH w/ production tbg. RIH w/ rods & pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Thomas Kacir TITLE Production Engineer DATE 9/14/99
TYPE OR PRINT NAME Thomas Kacir TELEPHONE NO. 393-7106

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

SEP 22 1999

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

