

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-34011
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	NEW MEXICO 'E' STATE NCT-2
8. Well No.	2
9. Pool Name or Wildcat	MONUMENT ABO
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3727'

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>F</u> : <u>2310</u> Feet From The <u>NORTH</u> Line and <u>2175</u> Feet From The <u>WEST</u> Line Section <u>23</u> Township <u>19-S</u> Range <u>36-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3727'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☒ ACIDIZE PERFS

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-10-98: MIRU. TOH W/RODS & PMP. TIH W/PARAFFIN KNIFE ON RDS TO 1500'. NDWH. NUBOP. TBG HAS FILM OF SCALE. TIH W/BIT & CSG SCRAPER ON 2 7/8" TBG TO 7665' (PBTD). PULL TO 5540'.  
7-11-98: KILL WELL W/40 BBLS 2% KCL. TOH W/TBG, SCRAPER & BIT. TIH W/PKR, SN, & 2 7/8" TBG. PSA 7336'. LOAD CSG W/100 BBLS 2% KCL. TEST CSG TO 500#-OK.  
7-13-98: PRESS AN TO 500 PSI. ACIDIZED 7400-7616' W/3500 GALS 15% NEFE. FLSH W/50 BBLS 2% KCL FW. REL PKR. TAG FILL @ 7660'. RAN SN, TA & TBG. KILL WELL W/20 BBLS 2% KCL FW. REM BOP. LAND SN @ 7651'. PUMP 50 BBLS 2% KCL FW DN TBG TO ELIMINATE H2S GAS. RAN GAS ANCHOR ON PUMP.  
7-14-98: RAN RDS W/LINER @ 7651'. LOAD TBG W/43 BBLS 2% KCL FW. SPACE PUMP @ 7". TEST TBG TO 500 PSI-OK. RIG DOWN. ON PRODUCTION @ 8:30 AM. PUMPING & TESTING.  
7-24-98: ON 24 HR OPT. PUMPED 74 BO, 88 BW, & 92 MCF. GOR-1243. GRAV-39.0 @60.  
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 7/27/98  
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS

APPROVED BY DISTRICT I SUPERVISOR TITLE  DATE AUG 10 1998

CONDITIONS OF APPROVAL, IF ANY: