

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-34067
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Laughlin
8. Well No. 2
9. Pool name or Wildcat Monument: Tubb

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Marathon Oil Company	
3. Address of Operator P.O. Box 2490 Hobbs, NM 88240	
4. Well Location Unit Letter G : 2310 Feet From The North Line and 2310 Feet From The East Line Section G Township 20-S Range 37-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) KB 3541' KB 3557'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **RC Paddock. Sqz new perfs. Return to Tubb** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 7/9 RU pulling unit. POOH w/pump & rods. ND wellhead. NU BOP. POOH w/tbg. RIH w/RBP, set at 6350'. Test RBP. OK. POOH w/tbg. RIH, pickle tbg w/750 gals 15% acid, POOH. RIH, log from 4600-5300'.
7/14 Perf Paddock 5166-5206 w/2SPF, 82 holes. RIH w/pkr, set at 5096. Acidize w/4000 gals 15% acid. Swab
7/19 Rel pkr & RBP, POOH w/both. RIH w/new RBP & pkr. Set RBP at 5268', pkr at 5265'. Test RBP, OK. Rel pkr. Dump 2 sxs sand. POOH w/pkr. RIH w/cmt retainer, set at 5071'.
7/20 Cmt sqz Paddock 5166-5206 w/500 gals Flochek & 150 sxs cmt. PUH. RIH w/rods. ND BOP NU wellhead. RD.
8/1 RU pulling unit. ND wellhead, NU BOP. POOH w/rods. POOH w/tbg. TIH w/bit, tag cmt at 5054'. DO cmt 5054-5206'. RIH, tag sand at 5256'. Clean out to RBP at 5268'. Test sqzd perfs to 500 psi, held OK. TOOH w/bit. TIH w/RBP overshot. Pickle tbg w/200 gals Xylene & 500 gals 15% HCL. Swab. Rel RBP, POOH. RIH w/PPI tools to 6589'. Acidize Tubb 6408-6589 w/3000 gals 15% acid. Reset pkr at 6350'. Swab. Rel pkr, POOH. RIH w/2 3/8" prod tbg. ND BOP. NU wellhead.
8/9 RIH w/pump & rods. Load & test. RD pulling unit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 8/15/00

TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

