Form 3160-5 (June 1990)

or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR RURFALL OF LAND MANAGEMENT

N.M. Oil Cons. Division P.O. Box 1980 Hobbs NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF LAND N	MANAGEMENT Hobbs, NM 8824	
		5. Lease Designation and Serial No. NM-84902
SUNDRY NOTICES AND R		6 If Indian Allottee or Tribe Name
Do not use this form for proposals to drill or to	deepen or reentry to a different reservoir.	
Use "APPLICATION FOR PERM	111 —" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well		-
Oil Gas Well Other 2. Name of Operator		8. Well Name and No.
·		Quail Federal #6
Read & Stevens, Inc. 3. Address and Telephone No.		30-025-34116
P. O. Box 1518 Roswell, New Mexico 88202-1518 505/622-3770 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2310' FNL & 990' FEL.		10. Field and Pool, or Exploratory Area
		NE Lea Delaware
		11. County or Parish, State
Section 3 T20S-R34E		
		Lea County, New Mexic
2. CHECK APPROPRIATE BOX(s) TO IN	NDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
I Prince As a second second	1 1	
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other Retrieve RBP, LD rods & pum etails, and give pertinent dates, including estimated date of starting	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Describe Proposed or Completed Operations (Clearly state all pertinent de	Other Retrieve RBP, LD rods & pum tails, and give pertinent dates, including estimated date of starting r all markers and zones pertinent to this work.)* Repump. Retrieve RBP & POH, lay turn well to production pump testing	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) g any proposed work. If well is directionally drilled down same. Rung Brushy Canyon rations. Currently
3. Describe Proposed or Completed Operations (Clearly state all pertinent de give subsurface locations and measured and true vertical depths for 10/02/98 MIRUPU. POH /w rods & rods & pump, EOT @ 8,026'. Ret Delaware perforations commingled w pump testing.	Other Retrieve RBP, LD rods & pum etails, and give pertinent dates, including estimated date of starting r all markers and zones pertinent to this work.)* Retrieve RBP & POH, lay turn well to production pump testin with Cherry Canyon Delaware performance of the performance of t	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) g any proposed work. If well is directionally drilled down same. Rung Brushy Canyon rations. Currently
3. Describe Proposed or Completed Operations (Clearly state all pertinent de give subsurface locations and measured and true vertical depths for 10/02/98 MIRUPU. POH /w rods & rods & pump, EOT @ 8,026'. Ret Delaware perforations commingled w pump testing.	etails, and give pertinent dates, including estimated date of starting rall markers and zones pertinent to this work.)* Repump. Retrieve RBP & POH, lay turn well to production pump testin with Cherry Canyon Delaware performance (ORIG. SGD.) DAVID R. OCT 21 1853 BLM.	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) g any proposed work. If well is directionally drilled down same. Rung Brushy Canyon rations. Currently
3. Describe Proposed or Completed Operations (Clearly state all pertinent de give subsurface locations and measured and true vertical depths for 10/02/98 MIRUPU. POH /w rods 8 rods & pump, EOT @ 8,026'. Ret Delaware perforations commingled w pump testing.	Other Retrieve RBP, LD rods & pum stails, and give pertinent dates, including estimated date of starting r all markers and zones pertinent to this work.)* Repump. Retrieve RBP & POH, lay turn well to production pump testin with Cherry Canyon Delaware performance (ORIG. SGD.) DAVID R.	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) g any proposed work. If well is directionally drilled down same. Rung Brushy Canyon rations. Currently
3. Describe Proposed or Completed Operations (Clearly state all pertinent de give subsurface locations and measured and true vertical depths for 10/02/98 MIRUPU. POH /w rods & rods & pump, EOT @ 8,026'. Ret Delaware perforations commingled w pump testing.	etails, and give pertinent dates, including estimated date of starting rall markers and zones pertinent to this work.)* Repump. Retrieve RBP & POH, lay turn well to production pump testin with Cherry Canyon Delaware performance (ORIG. SGD.) DAVID R. OCT 21 1853 BLM.	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) g any proposed work. If well is directionally drilled down same. Rung Brushy Canyon rations. Currently
3. Describe Proposed or Completed Operations (Clearly state all pertinent de give subsurface locations and measured and true vertical depths for 10/02/98 MIRUPU. POH /w rods & rods & pump, EOT @ 8,026'. Ret Delaware perforations commingled w pump testing.	etails, and give pertinent dates, including estimated date of starting rall markers and zones pertinent to this work.)* Repump. Retrieve RBP & POH, lay turn well to production pump testin with Cherry Canyon Delaware performance (ORIG. SGD.) DAVID R. OCT 21 1853 BLM.	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) g any proposed work. If well is directionally drilled down same. Rung Brushy Canyon rations. Currently