

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-34341
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name W.H. Laughlin
8. Well No. 8
9. Pool name or Wildcat Monument; Abo
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3545' KB 3558'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Marathon Oil Company

3. Address of Operator
P.O. Box 2409 Hobbs, NM 88240

4. Well Location
Unit Letter **F** : **1760** Feet From The **North** Line and **1750** Feet From The **West** Line
Section **9** Township **20-S** Range **37-E** NMPM **Lea** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GL 3545' KB 3558'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: New Well Completion <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/8 MIRU PU. ND wellhead. NU BOP. DO to 7770'. Clean out.
5/10 Perf 7284-97, 7303-18, 7342-76, 7393-7402, 7406-16, 7419-24, w/2 SPF 120 deg phas. Acidize w/11,300 gals 15% acid w/250 BS. Swab well.
5/14 Cmt sqz 7284-7424 w/1000 gals Flochek & 400 sxs cmt. (1st attempt w/350 sxs failed). DO to 7426'. Test sqzd perfs to 1000 psi, OK.
5/17 Perf 7205-10, 7215-25, 7232-62, w/2 SPF, 120 deg phas. Acidize w/4600 gals 15% acid w/130 BS.
5/21 RIH w/4 1/2" CIBP. Set at 7280'. Cmt sqz 7205-7262 w/500 sxs cmt. Test sqzd perfs to 1000 psi, OK.
5/28 Perf 7082-88, 7092-7100, 7104-08, 7156-80, w/4 SPF, 120 deg phas. Acidize w/2000 gals 15% acid.
6/2 Acidize lower perfs 7156-80 w/2500 gals 15% acid. Swab well. Rel pkr at 7063' and RBP at 7195'. POOH w/both.
6/5 RIH w/2 3/8" prod tbg. ND BOPE. NU wellhead. RIH w/pump & rods. RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 6/9/98

TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

APPROVED BY _____ TITLE _____ DATE JUL 1 1998

CONDITIONS OF APPROVAL, IF ANY: _____