	Submit 3 Copies To Appropriate Dis Office	strict Stat	te of New N	lexico		Form C-103	
	District I			tural Resources	Revised March 25, 1999		
	1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO). 5-34807	
	811 South First, Artesia, NM 88210 District III		OIL CONSERVATION DIVISION			e of Lease	
	1000 Rio Brazos Rd., Aztec, NM 874					FEE	
	District IV	rice IV Santa Fe, NM 87505				Gas Lease No.	
	220 S. St. Francis Dr., Santa Fe, NM 7505						
		NOTICES AND REPORT		-04576 or Unit Agreement Name:			
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:					or onit Agreement Name.	
	Oil Well 🔲 Gas We	State 2-M					
	2. Name of Operator Threshold Development Company (817-870-1483)					8. Well No.	
Ì	3. Address of Operator				9. Pool name or Wildcat		
	777 Taylor St S	777 Taylor St Suite II-D - Fort Worth, TX 76102				Undes. Bone Springs	
	4. Well Location	· · · · · · · · · · · · · · · · · · ·	<u>^</u>				
	Unit Letter M	<u>: 660</u> feet from	the South	line and	660 feet fro	om the <u>West</u> line	
	Section 2	Township			NMPM Lea	County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3675' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
	PERFORM REMEDIAL WORK			SUB	SEQUENT RE		
				. REMEDIAL WORI			
	TEMPORARILY ABANDON	CHANGE PLANS			LLING OPNS. 🔲		
	PULL OR ALTER CASING			CASING TEST AN		ABANDONMENT	
		COMPLETION		CEMENT JOB	THE COMMISSI	ON MUST BE NOTIFIED 24	
	OTHER:			OTHER:	PILIGGING OP	TO THE BEGINNING	
_	2. Describe proposed or com	pleted operations. (Clearl	y state all per	tinent details, and gi		ERATIONS FOR THE C-TO3	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates Fincluding estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion							
or recompnation.							
Threshold Development Company respectfully requests permission to plug and abandon this well as follows:							
1. Nipple up BOP. Release tubing anchor. TOOH with tubing. Load casing with produced							
	2. Wireline set CIBP at 9800' and cap with cement.						
	3. TIH with tubing and tag CIBP at 9800'. Load hole with plugging mud or 25#/bbl salt-						
	water gel in produced water. TOOH with tubing. 4. Stretch casing to determine freepoint. Cut at 9000' and pull casing. Spot a 25 sack						
	5. Spot a 40 sack Class "H" cement plug from 7000-6900'. POOH with tubing to 5300'						
 6. Spot a 50 sack Class "H" cement plug 50' in and 50' out of intermediate casing shoe (5300-5200'). 7. POOH with tubing to 1940'. Spot a 35 sack Class "C" cement with 2% CaCl2 50' below and above anhydrite top (1940-1840'). POOH with tubing to 703'. I hereby certify that the information above is true and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE: 						te casing shoe	
CONTINUED ON NEXT PAGE:						2 :	
· S	IGNATURE WITH	fin		gent for Thres	hold Dev. Co.		
Ţ	ype or print name Rusty Kle	ein			Telenh	one No. 746-6565	
5 (1	his space for State use)						
· ^	PPPROVED BY		ንግም፤ ኮ	GUIGINAL SIGNE		JUL 1 6 2002	
	onditions of approval, if any:		TITLE	PAULE KAU		_DATE	
			4	TROPHIM ENG	INFER		

THRESHOLD DEVELOPMENT COMPANY State 2-M #1 Section 2-T20S-R35E Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

8. Spot a 35 sack Class "C" cement plug with 2% CaCl2 from 703-603' (50' in and 50' out of surface casing).

9. Spot a 35 sack Class "C" cement plug with 2% CaCl2 from 120' to surface.

10. Install regulation abandonment marker.

NOTIFY OCD-HOBBS (505-393-6161, EXT. 112 or 114) 24 HOURS PRIOR TO COMMENCING PLUGGING OPERATIONS

Rusty Klein

Agent for Threshold Development Company July 12, 2002



BEFORE



AFTER



Threshold Development Company

not to scale