Laughlin #1 Lea Co., NM		30-025-34975 Trade agreement: 1026308
5-4-00	Prepare to MI & RU well service unit. Banta Oil Field Service backhoe clean & level location. Fill cellar w/ dirt & pea gravel. T & C Anchor set & test deadman anchors.	
5-5-00	MI & RU Lucky Services #13. NU 4-1/2" screw on x 7-1/16" 5M tbg head. NU 7-1/16" 3M BOP. RU Lea Fishing Tool Reverse Unit & pump. Unload & strap 236 jts 2-3/8" 4.7# J-55 8rd EUE tbg. Total = 7590.10' thrds off. PU 3-7/8" bit, BS, 4 3-1/2" DC's & XO. PU & TIH w/ tbg. Tag up @ 4789'. Drill out cement & DV tool @ 4807' in 1-1/2 hrs. Circ clean. Test 4-1/2" csg to 1000# for 5 min. OK. LD swivel. TOH & PU csg scraper. TIH & work scraper @ 4807'. PU & TIH w/ tbg to 4951'. Secure well & shut down for night.	
5-6-00	Continue PU & TIH w/ 2-3/8" tbg. Tag PBTD @ 7228'. Circ hole clean. Recovered soft cement off btm. LD 9 jts tbg to 6923'. RU Freemyer Tech Service. Test 4-1/2" csg to 1500 psi for 5 min, OK. Circ hole w/ 2% KCL & spot 420 gal 15% HCL w/ additives from 6923' to 6280". TOH w/ 208 jts tbg. LD BHA. RU JSI Wireline. Run CBL from 7236' to 4700'. Secure well shut down for night.	
5-7-00 JSI perforated Lower Drinkard from 6863' to 6883' (80 holes) 4 SPF csg gun. RD wireline. PU pkr & TIH w/ 2-3/8" tbg. Tubing detail:		883' (80 holes) 4 SPF 90 deg phasing w/ 3-3/8" ' tbg.
	KB correction	10.00'
	208 jts 2-3/8" 4.7# J55 8rd EUE tbg	6702.23'
	4-1/2" x 2-3/8" Arrow Set 1X pkr	6.16'
	1 jt 2-3/8" 4.7# J55 tail pipe	32.42'
	"XN" nipple, 1.875" profile, 1.791" NOGO	1.40'
	2-3/8" 4.7# J55 tbg sub	8.04'
	2-3/8" muleshoe W.L.R.G.	<u>.41'</u>
	End of tbg @	6760.66'
	Top of pkr @	6712.23'
	ND BOP, NU 7-1/16" x 2-1/16" 5M tree & wrap around. Rev circ 10 bbl 2% KCL down annulus. Set pkr @ 6712' w/ 8K compression & land tree. Test annulus to 500# OK. RU Freemyer Tech Serv. Break formation down @ 4990 psi. Pump into perfs @ 1/2 BPM @ 5000 psi, press break to 4600 psi, incr to 1.1 BPM @ 5050 psi. ISIP 4880, 5 min 3720, 10 min 3010, 15 min 2400 (38.8 BLWTR). Connect flow & swab tank. Open well w/ 1200 psi, flow back 1/2 BLW. RU swab well 4 hrs, IFL @ surface. FFL @ 6200'. Wait 30 min between runs last 2 hrs. Trace oil & gas. Total fluid recovered, flow & swab = 36.5 BLW (2.3 BLWTR). Secure well & SDFN.	
5-8-00	12 hr SITP 0 psi. RU swab. IFL @ 3000', 12.38 bbl fluid entry over night. Swab well 3 hrs, FFL @ 6200'. Recovered 17 BW (14.7 bbl over load). Trace oil & gas. Wait 30 min between runs last hr. Secure well & shut down for Sunday.	