District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Re

Form C-101 Revised March 17, 1999

Oil Conservation Division 2040 South Pacheco Santa Fe, NM 87505

Submit to appropriate District Office
State Lease - 6 Copies
Fee Lease - 5 Copies

AMENDED REPORT

		1	PERMIT 7 Operator Name an	d Address	<u> </u>			OGRID Number		
			oration				025482			
PO Box 352 Midland, Texas 79702							30 - \$25 - 025 - 35334 Weil No.			
Property Code Property N					Property Name	e "Well No.			l No.	
/_	087	<u>*</u>	Chardon			<del> </del>		# 1		
	T -	· · · · · · · · · · · · · · · · · · ·	<del></del>	Su	rface Locatio	<b>n</b>	<del></del>	ı	<del></del>	
UL or lot no. Section		Township	Range	Lotida	Feet from the	North/South line	Feet from the	East/West line	County	
3	14	198	38E		1980	North	2080	East	Lea	
		8	Proposed P	ottom Hole	Location If I	Different Fron	n Surface	,		
/L or lot no.	Section	Township	Range	Lot idn	Feet from the	North/South line	Feet from the	East/West line	County	
Indino	l Drinka:		Proposed Pool I	1	<u> </u>	Bline	ory Oil &	ged Pool 2 Gas	<u> </u>	
authe	DI IIIKa.	I d ABO		·		2.7.2	<u> </u>	<u></u>	<del></del>	
N O		12 Well Type Co	Code 13 Cable/Rotary			Legge Type Code	" Ground Level Elevation			
			O "Proposed Depth 8,500 '		R 8		P	361	3618 Spud Date ASAP	
							"Contractor Energy Co.	٨٥٨		
				Proposed Co	<del></del>	nent Program		ASA	<u> </u>	
Hole :	ize.	Car		Casing weigh				- I	Estimated TOC	
12 1/4			Casing Size         Casing wei           8 5/8         24			Setting Depth		Sacks of Cement		
7 7/8		<del></del>					00' 850 00' 900		Circulated	
. ,, ,				F / C		900		Circ-Surfac		
	<del></del>	1			<del></del>		<del> </del>		· • •	
		-				<del></del>			<del>.</del>	
···						· - · · · · · · · · · · · · · · · · · ·			<del></del>	
	ne proposed i	program. If th	is application is t	o DEEPEN or PL	UG BACK, give th	e data on the presen	t productive zone a	nd proposed new	productive zone.	
Describe ti			ifa ( ta ad							
	Nowout prev	ention progra	mi, mamy. Ose aki	ditional sheets if n	necessary.					
escribe the l	11 12	1/4" ho	le to app	roximate]	Ly 1600' o:	r hard for	mation w/f	resh wate	er	
Dri Set	11 12 8 5/8	1/4" ho " csg &	le to app	oroximatel 1/650 sx '	Ly 1600' o:		mation w/f c1 + 200 s	resh wate x "C" + 2	er 2% Calc;	
Dri Set cir	11 12 8 5/8 culate	1/4" ho " csg & cement	le to appoint of the cement with the surface of the cement with the cement with the cement of the ce	proximatel 1/650 sx ' nce	Ly 1600' or 'C" + 4% g	r hard for el + 2% Ca	c1 + 200 s	x "C" + 2	er 2% Calc;	
Dri Set cir Dri	11 12 8 5/8 culate 11 7 7	1/4" ho " csg & cement /8" ho1	le to approximate to surface with br	proximatel 1/650 sx ' nce ine water	Ly 1600' or 'C" + 4% g	r hard for el + 2% Ca . Run ope	c1 + 200 s	sx "C" + 2	2% Calc;	
Dri Set cir Dri Set	11 12 8 5/8 culate 11 7 7 5 1/2	1/4" ho " csg & cement /8" ho1 " csg.	le to app cement w to surfa e with br Cement w	oroximatel 7/650 sx ' ace sine water 7/555 sx '	ly 1600' of 'C" + 4% go to 8500' 'C" 35:65:	r hard for el + 2% Ca . Run ope poz + 6%	c1 + 200 s	sx "C" + 2	2% Calc;	
Describe the I  Dri  Set  cir  Dri  Set	11 12 8 5/8 culate 11 7 7 5 1/2	1/4" ho " csg & cement /8" ho1 " csg.	le to app cement w to surfa e with br Cement w	oroximatel 7/650 sx ' ace sine water 7/555 sx '	Ly 1600' or 'C" + 4% g	r hard for el + 2% Ca . Run ope poz + 6%	c1 + 200 s	sx "C" + 2	2% Calc;	
Describe the U  1. Dri 2. Set cir 3. Dri 4. Set cel	11 12 8 5/8 culate 11 7 7 5 1/2 loflak	1/4" ho " csg & cement /8" ho1 " csg. e; tail	le to approximate to surface with brace with www. 345 sx	oroximatel 7/650 sx ' ace sine water 7/555 sx '	ly 1600' or 'C" + 4% go to 8500' 'C" 35:65:	r hard for el + 2% Ca . Run ope poz + 6% surface	c1 + 200 s n hole log ge1 + 5% s	sx "C" + 2 gs. salt + .25	2% Calc;	
Describe the I 1. Dri 2. Set cir 3. Dri 4. Set cel	11 12 8 5/8 culate 11 7 7 5 1/2 loflak	1/4" ho " csg & cement /8" ho1 " csg. e; tail	le to approximate to surface with brace with www. 345 sx	oroximatel n/650 sx ' nce nine water n/555 sx ' c "C"; cir	ly 1600' or 'C" + 4% go to 8500' 'C" 35:65:	r hard for el + 2% Ca . Run ope poz + 6% surface	c1 + 200 s n hole log gel + 5% s	ix "C" + 2 iss. isalt + .25	2% Calc;	
Describe the I	11 12 8 5/8 culate 11 7 7 5 1/2 loflak	1/4" ho " csg & cement /8" ho1 " csg. e; tail	le to approximate to surface with brace with www. 345 sx	oroximatel n/650 sx ' nce nine water n/555 sx ' c "C"; cir	ly 1600' or 'C" + 4% go to 8500' 'C" 35:65: reculate to	r hard for el + 2% Ca . Run ope poz + 6% surface	c1 + 200 s n hole log gel + 5% s	ix "C" + 2 iss. isalt + .25	2% Calc;	
Describe the I 1. Dri 2. Set cir 3. Dri 4. Set cel 1 hereby comy knowledge Signature:	11 12 8 5/8 culate 11 7 7 5 1/2 loflak	1/4" ho " csg & cement /8" ho1 " csg. e; tail	le to approximate with brown Cement wow w/345 sx	oroximatel n/650 sx ' nce nine water n/555 sx ' c "C"; cir	ly 1600' or 'C" + 4% go to 8500' 'C" 35:65: reculate to	r hard for el + 2% Ca  Run ope poz + 6% surface  OIL (	c1 + 200 s n hole log gel + 5% s	ix "C" + 2 iss. isalt + .25	2% Calc;	
Describe the I  1. Dri 2. Set cir 3. Dri 4. Set cel  1 hereby ce my knowled Signature:	11 12 8 5/8 culate 11 7 7 5 1/2 loflak	1/4" ho " csg & cement /8" ho1 " csg. e; tail	le to approximate with brown Cement wow w/345 sx	oroximatel n/650 sx ' nce nine water n/555 sx ' c "C"; cir	ly 1600' or 'C" + 4% go to 8500' 'C" 35:65: cculate to the best of App	r hard for el + 2% Ca  Run ope poz + 6% surface  OIL (	c1 + 200 s n hole log gel + 5% s	ix "C" + 2 iss. isalt + .25	SION CHPIS WILLIFERWISON	
Describe the l  1. Dri  2. Set cir  3. Dri  4. Set cel  1 hereby ce my knowled Signature:  Printed name	11 12 8 5/8 culate 11 7 7 5 1/2 loflak	1/4" ho " csg & cement /8" ho1 " csg. e; tail cinformation; C. Barn sident	le to approximate with brown Cement wow w/345 sx	oroximatel n/650 sx ' nce nine water n/555 sx ' c "C"; cir	ly 1600' or 'C" + 4% great to 8500' 'C" 35:65: cculate to the best of App	r hard for el + 2% Ca  Run ope poz + 6% surface  OIL Coved by:	c1 + 200 s n hole log gel + 5% s CONSERVA	IN "C" + 2  ISS.  Salt + .25  ITON DIVI	SION CHERS WILLS	

Z m