Office District I		New Mexico			Form C	-103
	Energy, Minerals an	nd Natural Resources	-]	Revised March 25,	, 1999
1625 N. French Dr., Hobbs, NM 87240			WELL AP	I NO.		
District II	OIL CONSERV	ATION DIVISION		<u>30-025-3562</u>	1	
811 South First, Artesia, NM 87210 District III		uth Pacheco	5. Indicate	5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe	STATE 😿 FEE 🗌				
2040 South Pacheco, Santa Fe, NM 87505			6. State Oil & Gas Lease No. N/A			
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPLI	CES AND REPORTS C OSALS TO DRILL OR TO D CATION FOR PERMIT" (FO	EEPEN OR PLUG BACK TO A		lame or Unit A	Agreement Name	= :
PROPOSALS.)			NORTH MON	UMENT / GRA	YEURG	İ
1. Type of Well: Oil Well 🕱 Gas Well	Oil Well 🕱 Gas Well 🗌 Other			SAN ANDRES UNIT ELK 16, NO. 29		
2. Name of Operator			8. Well No).		\dashv
merada Hess Corporation			327			
3. Address of Operator				9. Pool name or Wildcat		
P.O. Box 2040 Houston, TX 77252-2040			1	EUNICE-MONUMENT G/S ANDRES		
4. Well Location		· · · · · · · · · · · · · · · · · · ·		ENCHEAVI G/S	ANLRES	\dashv
Unit Letter <u>L</u> :	1385 feet from the	SOUTH line and	185	feet from the_	WEST	line
Section 32	Township 1		NMPM	Cor	unty LEA	
	10. Elevation (Show v	whether DR, RKB, RT, GR, 3565' GR.	etc.)			
11. Check /	Appropriate Box to Ir	idicate Nature of Notice	Report or	Other Data	<u> </u>	
NOTICE OF INT			=			
			BSEQUEN		= -	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	I ☐ REMEDIAL WORK		L ALT	TERING CASING	⊒ ن
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL	LING OPNS.		JG AND	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST ANI)	X AB	ANDONMENT	
OTHER:		OTHER: Rumning	Gurfaco Con	-1		x
	ed Operations (Clearly sta	ate all pertinent details, and	give pertinent	dates, including	ng estimated date	;
12. Describe Proposed or Complete of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. Somill from 1040' to 1150' jts of 8-5/8", 24#, J55, Girc Car. Out w/ BJ: Proposed to 1250' proposed to 1	SEE RULE 1103. For M Spud well @ 15:00 1 urvey @ 492' = 3/4 (1 Survey @ 1123' = 1. 8RD, ST&C, 'A' csg se	HRS 08-31-01. (40' of 1 Deg.). Drill from 532' .00 (Deg). Circ and cor et @ 1150', Shoe @ 1149	.4" Conducto to 1040'. S nd. RU Bull 1	r + 12' To 1 urvey @ 999 Rogers Csg (3' & ran 10	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. So Drill from 1040' to 1150' jts of 8-5/8", 24#, J55, Circ Csg. Cmt w/ BJ: Pump	SEE RULE 1103. For M . Spud well @ 15:00 1 urvey @ 492' = 3/4 (1 . Survey @ 1123' = 1. 8RD, ST&C, 'A' csg se 250 sx of class 'C'	ERS 08-31-01. (40' of 1 Deg.). Drill from 532' .00 (Deg). Circ and cor et @ 1150', Shoe @ 1149 + 2% Cacl2 + 1/4#/sx 0	.4" Conducto to 1040'. So d. RU Bull 1 '', FC @ 110: F (13.7#-1.	r + 12' To ; urvey @ 999 Rogers Csg (3' & ran 10 56). Taile	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. So Drill from 1040' to 1150' jts of 8-5/8", 24#, J55, 30 Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4	SEE RULE 1103. For M Spud well @ 15:00 1 urvey @ 492' = 3/4 (1 Survey @ 1123' = 1. 8RD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35)	ERS 08-31-01. (40' of 1 Deg.). Drill from 532' .00 (Deg). Circ and cor et @ 1150', Shoe @ 1149 + 2% Cacl2 + 1/4#/sw 0	.4" Conductor to 1040'. So nd. RU Bull 1 0', FC @ 1101 F (13.7#-1.0 prime water (r + 12' To ; urvey @ 999 Rogers Csg (3' & ran 10 66). Tailed 3 6 bbl/min	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. Somill from 1040' to 1150' jts of 8-5/8", 24#, J55, Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4 w/450 psi. Bump plug w/ 9	SEE RULE 1103. For M Spud well @ 15:00 1 urvey @ 492' = 3/4 (1 Survey @ 1123' = 1. BRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs v	HRS 08-31-01. (40' of 1 Deg.). Drill from 532' .00 (Deg). Circ and cor et @ 1150', Shoe @ 1149 + 2% Cacl2 + 1/4#/sx (). Displace w/ 71 bbl h w/ good returns. Circ 1	.4" Conductor to 1040'. So nd. RU Bull 1 0', FC @ 1101 F (13.7#-1.0 prime water (r + 12' To ; urvey @ 999 Rogers Csg (3' & ran 10 66). Tailed 3 6 bbl/min	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. So Drill from 1040' to 1150' jts of 8-5/8", 24#, J55, 30 Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4	SEE RULE 1103. For M Spud well @ 15:00 1 urvey @ 492' = 3/4 (1 Survey @ 1123' = 1. BRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs v	HRS 08-31-01. (40' of 1 Deg.). Drill from 532' .00 (Deg). Circ and cor et @ 1150', Shoe @ 1149 + 2% Cacl2 + 1/4#/sx (). Displace w/ 71 bbl h w/ good returns. Circ 1	.4" Conductor to 1040'. So nd. RU Bull 1 0', FC @ 1101 F (13.7#-1.0 prime water (r + 12' To ; urvey @ 999 Rogers Csg (3' & ran 10 66). Tailed 3 6 bbl/min	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. Somill from 1040' to 1150' jts of 8-5/8", 24#, J55, Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4 w/450 psi. Bump plug w/ 9	SEE RULE 1103. For M Spud well @ 15:00 1 urvey @ 492' = 3/4 (1 Survey @ 1123' = 1. BRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs v	HRS 08-31-01. (40' of 1 Deg.). Drill from 532' .00 (Deg). Circ and cor et @ 1150', Shoe @ 1149 + 2% Cacl2 + 1/4#/sx (). Displace w/ 71 bbl h w/ good returns. Circ 1	.4" Conductor to 1040'. So nd. RU Bull 1 0', FC @ 1101 F (13.7#-1.0 prime water (r + 12' To ; urvey @ 999 Rogers Csg (3' & ran 10 66). Tailed 3 6 bbl/min	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. Somill from 1040' to 1150' jts of 8-5/8", 24#, J55, Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4 w/450 psi. Bump plug w/ 9	SEE RULE 1103. For M Spud well @ 15:00 1 urvey @ 492' = 3/4 (1 Survey @ 1123' = 1. BRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs v	HRS 08-31-01. (40' of 1 Deg.). Drill from 532' .00 (Deg). Circ and cor et @ 1150', Shoe @ 1149 + 2% Cacl2 + 1/4#/sx (). Displace w/ 71 bbl h w/ good returns. Circ 1	.4" Conductor to 1040'. So nd. RU Bull 1 0', FC @ 1101 F (13.7#-1.0 prime water (r + 12' To ; urvey @ 999 Rogers Csg (3' & ran 10 66). Tailed 3 6 bbl/min	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. Somill from 1040' to 1150' jts of 8-5/8", 24#, J55, Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4 w/450 psi. Bump plug w/ 9	SEE RULE 1103. For M Spud well @ 15:00 1 urvey @ 492' = 3/4 (1 Survey @ 1123' = 1. BRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs v	HRS 08-31-01. (40' of 1 Deg.). Drill from 532' .00 (Deg). Circ and cor et @ 1150', Shoe @ 1149 + 2% Cacl2 + 1/4#/sx (). Displace w/ 71 bbl h w/ good returns. Circ 1	.4" Conductor to 1040'. So nd. RU Bull 1 0', FC @ 1101 F (13.7#-1.0 prime water (r + 12' To ; urvey @ 999 Rogers Csg (3' & ran 10 66). Tailed 3 6 bbl/min	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. So Drill from 1040' to 1150' jts of 8-5/8", 24#, J55, 6 Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4 w/450 psi. Bump plug w/ 9 rams & casing w/ 1000 psi	SEE RULE 1103. For M. Spud well @ 15:00 purvey @ 492' = 3/4 (1) Survey @ 1123' = 1. SRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs w, OK. Drill cmt from	HRS 08-31-01. (40' of 1 Deg.). Drill from 532'. 00 (Deg). Circ and coret @ 1150', Shoe @ 1149' + 2% Cacl2 + 1/4#/sx 0). Displace w/ 71 bbl kw/ good returns. Circ 1 1100' - 1149'.	4" Conductor to 1040'. So cd. RU Bull 1 '', FC @ 110: F (13.7#-1.0 Trine water (33 sx cmt to	r + 12' To ; urvey @ 999 Rogers Csg (3' & ran 10 66). Tailed 3 6 bbl/min	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. So Drill from 1040' to 1150' jts of 8-5/8", 24#, J55, 6 Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4 w/450 psi. Bump plug w/ 9 rams & casing w/ 1000 psi	SEE RULE 1103. For M. Spud well @ 15:00 purvey @ 492' = 3/4 (1) Survey @ 1123' = 1. SRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs w, OK. Drill cmt from	HRS 08-31-01. (40' of 1 Deg.). Drill from 532'. 00 (Deg). Circ and coret @ 1150', Shoe @ 1149' + 2% Cacl2 + 1/4#/sx 0). Displace w/ 71 bbl kw/ good returns. Circ 1 1100' - 1149'.	4" Conductor to 1040'. So cd. RU Bull 1 '', FC @ 110: F (13.7#-1.0 Trine water (33 sx cmt to	r + 12' To ; urvey @ 999 Rogers Csg (3' & ran 10 66). Tailed 3 6 bbl/min	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. S Drill from 1040' to 1150' jts of 8-5/8", 24#, J55, Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4 w/450 psi. Bump plug w/ 9 rams & casing w/ 1000 psi,	SEE RULE 1103. For M. Spud well @ 15:00 purvey @ 492' = 3/4 (1) Survey @ 1123' = 1. SRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs w, OK. Drill cmt from	HRS 08-31-01. (40' of 1 Deg.). Drill from 532'. 00 (Deg). Circ and coret @ 1150', Shoe @ 1149' + 2% Cacl2 + 1/4#/sx 0). Displace w/ 71 bbl kw/ good returns. Circ 1 1100' - 1149'.	4° Conductor to 1040'. So d. RU Bull 1 ', FC @ 110: F (13.7#-1.0 rine water (33 sx cmt to	r + 12' To purvey @ 999 Rogers Csg (3' & ran 10 66). Tailed 6 bbl/min o pit. WOC	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ Test pipe).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. So Drill from 1040' to 1150' jts of 8-5/8", 24#, J55, Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4 w/450 psi. Bump plug w/ 9 rams & casing w/ 1000 psi, mereby certify that the information above	SEE RULE 1103. For M. Spud well @ 15:00 I urvey @ 492' = 3/4 (I. Survey @ 1123' = 1. BRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs w. OK. Drill cmt from	HRS 08-31-01. (40' of 10eg.). Drill from 532' .00 (Deg). Circ and coret @ 1150', Shoe @ 1149' + 2% Cacl2 + 1/4#/sx (0). Displace w/ 71 bbl hw/ good returns. Circ 11100' - 1149'.	4" Conductor to 1040'. So d. RU Bull 1 '', FC @ 110: F (13.7#-1.0 Trine water (33 sx cmt to	r + 12' To purvey @ 999 Rogers Csg @ 3' & ran 10 66). Tailed & 6 bbl/min o pit. WOC	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx . Final circ . Test pipe).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. S Drill from 1040' to 1150' jts of 8-5/8", 24#, J55, Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cac12 + 1/4 w/450 psi. Bump plug w/ 9 rams & casing w/ 1000 psi, mereby certify that the information above (GNATURE Man Williams	SEE RULE 1103. For M. Spud well @ 15:00 I urvey @ 492' = 3/4 (I. Survey @ 1123' = 1. BRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs w. OK. Drill cmt from	HRS 08-31-01. (40' of 10eg.). Drill from 532' .00 (Deg). Circ and coret @ 1150', Shoe @ 1149' + 2% Cacl2 + 1/4#/sx (0). Displace w/ 71 bbl hw/ good returns. Circ 11100' - 1149'.	4" Conductor to 1040'. So d. RU Bull 1 '', FC @ 110: F (13.7#-1.0 Trine water (33 sx cmt to	r + 12' To purvey @ 999 Rogers Csg @ 3' & ran 10 66). Tailed & 6 bbl/min o pit. WOC	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ Test pipe).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. So Drill from 1040' to 1150' jts of 8-5/8", 24#, J55, Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cacl2 + 1/4 w/450 psi. Bump plug w/ 9 rams & casing w/ 1000 psi, mereby certify that the information above	SEE RULE 1103. For M. Spud well @ 15:00 I urvey @ 492' = 3/4 (I. Survey @ 1123' = 1. BRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs w. OK. Drill cmt from	HRS 08-31-01. (40' of 10eg.). Drill from 532' .00 (Deg). Circ and coret @ 1150', Shoe @ 1149' + 2% Cacl2 + 1/4#/sx Color of 100' - 1149'. best of my knowledge and believed the state of t	4" Conductor to 1040'. So d. RU Bull 1 '', FC @ 110: F (13.7#-1.0 Trine water (33 sx cmt to	r + 12' To invey @ 999 Rogers Csg (3' & ran 10 66). Tailed a 6 bbl/min o pit. WOC	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx Final circ Test pipe 09/05/01 713-609-483).
of starting any proposed work). or recompilation. 08-31-01 thru 09-02-01 MI & RU Patterson Rig #65 Drill from 52' to 532'. S Drill from 1040' to 1150' jts of 8-5/8", 24#, J55, Circ Csg. Cmt w/ BJ: Pump class 'C' + 2% Cac12 + 1/4 w/450 psi. Bump plug w/ 9 rams & casing w/ 1000 psi, mereby certify that the information above (GNATURE Man Williams	SEE RULE 1103. For M. Spud well @ 15:00 I urvey @ 492' = 3/4 (I. Survey @ 1123' = 1. BRD, ST&C, 'A' csg se 250 sx of class 'C' 4#/sx CF (14.8#-1.35) 900 psi @ 18:00 hrs w. OK. Drill cmt from	ERS 08-31-01. (40' of 1 Deg.). Drill from 532' .00 (Deg). Circ and coret @ 1150', Shoe @ 1149' + 2% Cacl2 + 1/4#/sx Coret	4" Conductor to 1040'. So rd. RU Bull 1 '', FC @ 110: F (13.7#-1.) rrine water (33 sx cmt to	r + 12' To invey @ 999 Rogers Csg (3' & ran 10 66). Tailed a 6 bbl/min o pit. WOC	KB = 52'). ' = 1.00 (Deg) Crew & run 25 centralizers. d w/ 200 sx . Final circ . Test pipe).