Submit 3 Copies To Appropriate District Office District ( 1625 N. French Dr., Hobbs, NM 87240		State of New Mexico Energy, Minerals and Natural Resources		Form C-10: Revised March 25, 199 WELL API NO.		
District II 811 South District III 1000 Rio S District IV	First, Artesia, NM 87210 frazos Rd., Aztec, NM 87410 Pacheco, Santa Fe, NM 87505	OIL CONSERVA 2040 South Santa Fe, N	Pacheco	5. Indicate Type STATE [ 6. State Oil & C	FEE X	
DIFFEREN PROPOSAL 1. Type o	JSE THIS FORM FOR PROPOSAI T RESERVOIR. USE "APPLICAT .S.)	ES AND REPORTS ON W LS TO DRILL OR TO DEEPEN ON FOR PERMIT (FORM C-	OR PLUG BACK TO A	Hé	· Unit Agreement Name: rradura	
2. Name	2. Name of Operator  Xeric Oil & Gas Corporation				8. Weil No. #1	
3. Addre				9. Pool name or Wildcat Nadine Drinkard Abo		
4. Weil I	P. O. Box	352, Midland, TX	79702	Nadine Di	IIIKAIU ADO	
U	nit Letter P :	850 feet from the So	outh line and 3	30 feet from	the <u>East</u> line	
Se	ection 15	Township 19S	Range 38E	NMPM Lea	County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3604 GR						
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING						
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT						
PULL OR A	<del></del>	ILTIPLE  MPLETION	CASING TEST AND		RBANDONMENT	
OTHER:				Letion Attemp		
of starti	be proposed or completed oping any proposed work). SEE	erations. (Clearly state ail ERULE 1103. For Multip	pertinent details, and give le Completions: Attach v	e pertinent dates, invellbore diagram of	cluding estimated date proposed completion	
	MIRU PU. Install BOP.					
9/20/01	Perforate Lower Abo form spf, total 124 holes. TIH v	nation from 7518-7526, 75: w/tubing. and packer. Set	58-7556, 7272-7590, 765 Packer @ 7401.	0-7676 using select	fire 3 ½" gun, 2	
9/21/01	Acidize Lower Abo with 3500 gals 20% NEFE. Put well on pump to test lower Abo.					
10/10/01	MIRU PU. Install BOP. POOH w/Rods & Pump.					
10/11/01	Release TAC & POOH w/tbg. Set RBP @ 7470. Perforate Upper Abo from 7254-7262, 7318-7326, 7354-7380, 7394-7404, 7420-7436, w/1SPF, total of 73 holes. TIH w/tbg & packer. Set Packer @ 7210.					
10/12/01	Acidize upper Abo w/5000 gals 20% NEFE. Catch RBP and reset packer @ 7210. SI well. Waiting on gas pipeline to flow test well.					
I hereby certif	y that the information above	is true and complete to the	e best of my knowledge a	nd belief.		
SIGNATURE	Unge tra	WORL TITLE	Production Anal		OATE 1/11/02 (915)683-3650	
Type or print		d -		Telephon	e No.	
(This space for State use)					JAN 2 9 2002	
APPPROVED BY		TTTLE_			ATE	
	mples and ir mel.			<u>, papin</u>		