

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-35692
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	BAXTER CULP 31
8. Well No.	5
9. Pool Name or Wildcat	MONUMENT; TUBB
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3560'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH ROAD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>P</u> : <u>330'</u> Feet From The <u>SOUTH</u> Line and <u>330'</u> Feet From The <u>EAST</u> Line Section <u>31</u> Township <u>19-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3560'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ SQZ BLINEBRY, RECOMPLETE TO TUBB

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-23-02: MIRU. TIH W/PKR & SET @ 6343. REL & SPOT 2 SX SAND TO 5000. TAG SAND @ 6390. SET PKR @ 6095. SET CIRC ON TBG TO 5589.
4-24-02: TIH T/CICR FR 5589 ON PROD TBG TO 6091 & SET. SHUT DN W/7 BBLS OR 30 SX CMT. DUMP 7 BBLS CMT. SET CIRC TO 5904.
SHUT DOWN PUMP. 4-25-02: TIH W/PKR & SET @ 5405. PULL PKR TO 5029 & SET. 4-26-02: TAG CMT @ 5348. DRILL CMT FR 5348-5491.
4-29-02: TAG TOC @ 5491. DO CMT 5491 TO CIRC @ 5904. PRESS TEST BLINEBRY SQZ PERFS 5660-5881 TO 500 PSI. 4-30-02: DO CIRC @
5904 & CMT TO CIRC @ 6091. PRESS TEST BLINEBRY PERFS 5970-6070 TO 500 PSI. 5-01-02: DO CIRC & CMT TO 6163. 5-02-02: DO CMT
6163-6320. PRESS TEST BTM SET OF PERFS 6198-6316 TO 500 PSI. TAG SAND @ 6385. WASH SAND OFF RBP TO 6400. TIH W/RBP RETR
HEAD ON TBG TO TOP OF RBP @ 6400. DISPL HLE W/2% KCL FW. 5-03-02: REL RBP @ 6400. TAG FILL @ 6654. PERF 6334-38, 6343-47,
6379-84, 6400-04,
6454-58. TIH W/PKR TO 6300. 5-06-02: TUBB PERFS 6334-6584. ACIDIZIE TUBB PERFS 6334-6458 W/2100 GALS 15% ANTI-SLUDGE HCL.
PICKLE W/800 GALS 15% HCL. ACIDIZE 6454-58, 400 GALS ACID, SET PPI PKRS. REV CIRC 18 BBLS ACID TO TANK. 5-07-02: ACIDIZE 6334-
6348 W/2100 GALS 15% ANTI-SLUDGE HCL. SPOT ACID TO EOT-6400-04 W/210 GALS ACID. 6379-84, 462 GALS ACID, 6343-47 COMMUNICATE
UP. 6334-38 W/400 GALS ACID. 6454-58 W/400 GALS ACID. SET PKR @ 6320. CSG ON VAC. BROKE DN SQZ'D BLINEBRY PERFS. RU SWAB.
TUBB PERFS 6334-6584 ON SITP 540 PSI. (ALL GAS). 5-09-02: TIH W/RBP & PKR TO 6330. SET RBP. SET PKR @ 6325. MOVE PKR TO 6144.
THEN TO 5956. , THEN 5581, THEN 5771. ENGAGE RBP. REL RBP & MOVE UP HOLE TO 6145. SET PKR @ 6113. REL PKR & SPOT 2 SX SAND
ON RBP. 5-10-02: TIH W/CICR & SET @ 5610. 5-13-02: TIH ON 2 7/8" PROD TBG. TAG CMT @ 5564. D/O CMT TO 5610. CIRC TO 5613. CMT
TO 5675. 5-14-02: D/O CMT 5675-6064. PRESS TEST SQZ TO 500 PSI-OK. 5-15-02: TIH W/RBP RETR HEAD. TAG SAND @ 6138. DISPL
HOLE W/CLEAN 2% KCL FW. WASH SAND OFF RBP. ENGAGE & REL RBP @ 6145. TIH W/PROD TBG. NDBOP. SET TAC @ 6251. 5-16-02:
TIH W/2 1/2"X1 3/4"X20 INSERT PUMP & RDS.

5-22-02: ON 24 HR OPT. PUMPING 30 BO, 65 WATER, & 39 MCF.

PLAN TO DHC DRINKARD, ABO & TUBB.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist DATE 10/29/2002
TYPE OR PRINT NAME Denise Leake Telephone No. 915-687-7375

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER

DATE NOV 25 2002

DeSoto/Nichols 12-93 ver 1.0

2A Monument Blinebry