1-	API 30-025-01798	Approval expires 12-31-50.
Form 9-331.a. (Feb. 1951) 5.110 9 100	20	Land Office Hobbs
AUG 6 190	2 (SUBMIT IN TRIPLICATE)	Lesse No. NM 0336
E W. STANDLI	EY UNITED STATES	
	ARTMENT OF THE INTERIOR	Unit
	GEOLOGICAL SURVEY	
	mylected 8-31-62	JUL 1 9 1962
	TICES AND REPORTS O	• • • • • • • • • •
		HOBBS, Len altheory
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATE	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOO	
NOTICE OF INTENTION TO TEST WATER SHOTA		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.		DONMENTX
NOTICE OF INTENTION TO PULL OR ALTER CAS	SING SUPPLEMENTARY WELL HISTOR	Υ
NOTICE OF INTENTION TO ABANDON WELL		
(INDICATE ABOVE	BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTH	ER DATA)
		July 17 19.62.
Federal Well No. 1 Concoon is located .19	80ft. from(N) line and660 ft. f	$\operatorname{rom} \left\{ \frac{\chi}{W} \right\}$ line of sec. 20
	-()	(w)
SW/4 NW/4 20 21 (1/ Sec. and Sec. No.)	2S 33E NMPM Twp.) (Range) (Meridian)	
Wildcat	Iea	New Mexico NOTED
(Field)	(County or Subdivision)	(State or Territory)
The elevation of the derrick floor a	bove sea level is ft.	( JUL %0 1962 )
The elevation of the derrick floor a		( JUL 10 1562 )
-	DETAILS OF WORK	UUL 10 1562
(C		JUL 40 1982 AUBBLE
(State names of and expected depths to objective ing	DETAILS OF WORK a sands; show sizes, weights, and lengths of proposed of points, and all other important proposed work)	
(State names of and expected depths to objective ing Received permission to plug	DETAILS OF WORK	gs were set as follows:
(State names of and expected depths to objective ing Received permission to plug 15 sax 370-425, bottom of ca	DETAILS OF WORK sands; show sizes, weights, and lengths of proposed of points, and all other important proposed work) and abandon well. Cement plug	gs were set as follows: ; 12 sax 4000-4050, base sa
(State names of and expected depths to objective ing Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3	DETAILS OF WORK sands; show sizes, weights, and lengths of proposed of points, and all other important proposed work) and abandon well. Cement plug asing; 50 sax 870-1100, Rustler	gs were set as follows: ; 12 sax 4000-4050, base sa 1 casing consists of 399 fe its are leveled. Location
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing.	DETAILS OF WORK a sands; show sizes, weights, and lengths of proposed work) and abandon well. Cement plug asing;50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pr	gs were set as follows: ; 12 sax 4000-4050, base sa l casing consists of 399 fe its are leveled. Location
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing.	DETAILS OF WORK a sands; show sizes, weights, and lengths of proposed of points, and all other important proposed work) and abandon well. Cement plug asing; 50 sax 870-1100, Rustler Sand; 10sax top surface. Total	gs were set as follows: ; 12 sax 4000-4050, base sa l casing consists of 399 fe its are leveled. Location eet.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing.	DETAILS OF WORK seands; show sizes, weights, and lengths of proposed of points, and all other important proposed work) and abandon well. Cement plug asing; 50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pu l depth of drilling was 5068 for	gs were set as follows: ; 12 sax 4000-4050, base sa l casing consists of 399 fe its are leveled. Location eet.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total	DETAILS OF WORK a sands; show sizes, weights, and lengths of proposed work) and abandon well. Cement plug asing;50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pl 1 depth of drilling was 5068 for AUS 8 3502	gs were set as follows: ; 12 sax 4000-4050, base sa l casing consists of 399 fe its are leveled. Location eet.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total	DETAILS OF WORK seands; show sizes, weights, and lengths of proposed of points, and all other important proposed work) and abandon well. Cement plug asing; 50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pu l depth of drilling was 5068 for	gs were set as follows: ; 12 sax 4000-4050, base sa l casing consists of 399 fe its are leveled. Location eet.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total	DETAILS OF WORK a sands; show sizes, weights, and lengths of proposed work) and abandon well. Cement plug asing;50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pl 1 depth of drilling was 5068 for AUS 8 3502	gs were set as follows: ; 12 sax 4000-4050, base sa l casing consists of 399 fe its are leveled. Location eet.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total	DETAILS OF WORK a sands; show sizes, weights, and lengths of proposed work) and abandon well. Cement plug asing; 50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pic 1 depth of drilling was 5068 for AUS 8 362 ceive approval in writing by the Geological Survey before	gs were set as follows: ; 12 sax 4000-4050, base sa l casing consists of 399 fe its are leveled. Location eet.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total I understand that this plan of work must re Company	DETAILS OF WORK seands; show sizes, weights, and lengths of proposed of points, and all other important proposed work) and abandon well. Cement plug asing;50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pic 1 depth of drilling was 5068 for AUG 8 362 ceive approval in writing by the Ceological Survey bef	gs were set as follows: ; 12 sax 4000-4050, base sa l casing consists of 399 fe its are leveled. Location eet.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total I understand that this plan of work must re Company	DETAILS OF WORK a sands; show sizes, weights, and lengths of proposed of proposed work) and abandon well. Cement plug asing; 50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pice 1 depth of drilling was 5068 for AUG 8 302 ceive approval in writing by the Ceological Survey bef By	gs were set as follows: ; 12 sax 4000-4050, base sa 1 casing consists of 399 fe its are leveled. Location eet.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total I understand that this plan of work must re Company	DETAILS OF WORK seands; show sizes, weights, and lengths of proposed of points, and all other important proposed work) and abandon well. Cement plug asing;50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pic 1 depth of drilling was 5068 for AUG 8 362 ceive approval in writing by the Ceological Survey bef	gs were set as follows: ; 12 sax 4000-4050, base sa 1 casing consists of 399 fe its are leveled. Location eet.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total I understand that this plan of work must re Company	DETAILS OF WORK  a sands; show sizes, weights, and lengths of proposed work) and abandon well. Cement plug asing; 50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pi depth of drilling was 5068 fe AUS 8 362 ceive approval in writing by the Geological Survey bef By Title Agent	gs were set as follows: ; 12 sax 4000-4050, base sa 1 casing consists of 399 fe its are leveled. Location eet. Solution Galaxy Fore operations may be commenced.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total I understand that this plan of work must re Company	DETAILS OF WORK  a sands; show sizes, weights, and lengths of proposed work) and abandon well. Cement plug asing; 50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pi depth of drilling was 5068 fe AUS 8 362 ceive approval in writing by the Geological Survey bef By Title Agent	gs were set as follows: ; 12 sax 4000-4050, base sa 1 casing consists of 399 fe its are leveled. Location eet.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total I understand that this plan of work must re Company	DETAILS OF WORK  a sands; show sizes, weights, and lengths of proposed work) and abandon well. Cement plug asing; 50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pi depth of drilling was 5068 fe AUS 8 362 ceive approval in writing by the Geological Survey bef By Title Agent	gs were set as follows: ; 12 sax 4000-4050, base sa 1 casing consists of 399 fe its are leveled. Location eet. Solution Galaxy Fore operations may be commenced.
(State names of and expected depths to objective Received permission to plug 15 sax 370-425, bottom of ca 35 sax 4900-5065, Delaware 3 of 8-5/8, 20# H-40 casing. ready for inspection. Total I understand that this plan of work must re Company	DETAILS OF WORK  a sands; show sizes, weights, and lengths of proposed work) and abandon well. Cement plug asing; 50 sax 870-1100, Rustler Sand; 10sax top surface. Total Steel marker is erected and pi depth of drilling was 5068 fe AUS 8 362 ceive approval in writing by the Geological Survey bef By Title Agent	gs were set as follows: ; 12 sax 4000-4050, base sa 1 casing consists of 399 fe its are leveled. Location eet. Solution Galaxy Fore operations may be commenced.