

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002506058
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	880140
7. Lease Name or Unit Agreement Name	WEIR, C. H. -B-
8. Well No.	1
9. Pool Name or Wildcat	SKAGGS DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter H : 1984 Feet From The NORTH Line and 660 Feet From The EAST Line Section 11 Township 20S Range 37E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CLEAN OUT & ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-12-01: MIRU KEY. UNABLE TO GET PLUNGER TO SURF. UNLOAD & RACK WS. BLOW WELL DN. KILL W/100 BBLS 2% KCL WTR. NDWH. NUBOP.
3-13-01: SWAB DN TBG. FOUND PLUNGER STUCK IN TBG. PULL 203 JTS TBG. TIH W/BIT, DC'S ON WS. TAG @ 6880'. PULL BIT TO 6576'.
3-14-01: TIH W/BIT & BAILER ON WS. CLEAN OUT SCALE 6880-6895'. TIH W/PKR, & SN ON TBG. STOP PKR @ 3562'.
3-15-01: TIH W/209 JTS 2 7/8" WS & PKR. SET PKR @ 6587'. LOAD & TEST W/90 BBLS 10# BRINE-OK.
3-19-01: ACIDIZE DRINKARD CSG PERFS 6616-6896 W/5000 GALS 15% NEFE HCL. RU SWAB. FL @ 4800. END FL @ 5300'.
3-20-01: FL @ 5900'. UNSET PKR. END FL @ 5900. TIH W/BIT ON WS. TAG @ 6894'. STOP BIT @ 4216'.
3-21-01: TIH W/PROD TBG. STOP SN @ 6789'. FL @ 5900. END FL @ 5900. RAISE SN TO 6577'.
3-22-01: RUN PARAFFIN KNIFE TO SN @ 6577'. FL @ 5900. TIH W/SN OPEN ENDED ON TBG. SN @ 6789'. SPOT 1000 GALS TOLULENE ACR PERFS. FLUSH W/26 BBLS 2% KCL WTR. PULL SN TO 6577'.
3-23-01: FL @ 5700. END FL @ 5900.
3-26-01: NDBOP. NUWH. LAND TBG W/203 JTS 2 3/8" TBG. SN @ 6588. LEFT OUT SPRING & PLUNGER ON WH. RIG DOWN.
5-01-01: ON 24 HR OPT. PUMPING 6 BO, 3 BW, & 108 MCF.

DRINKARD PERFS 6166-6896

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 5/31/01
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED _____ DATE _____
CONDITIONS OF APPROVAL IF ANY: _____ TITLE: _____ DATE: _____