

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088

DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30 025 06073
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	879910
7. Lease Name or Unit Agreement Name	WEIR, C. H. -A-
8. Well No.	7
9. Pool Name or Wildcat	WEIR BLINEBRY EAST

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>L</u> 1985 Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>12</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, H I, GR, etc.)	3578' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☒ ALTERING CASING ☐ COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-04-98: MIRU. TOH W/RDS & PMP. KILL WELL., REL TAC. NUBOP. TIH W/BIT & CSG SCRAPER TO 2248'.
5-05-98: TIH TO 6842'. NO FILL. TIH W/RBP & PKR ON 2 3/8" TBG. TEST TO 5000#. SET RBP @ 6014'. PRESS UP ON RBP TO 1000#-NO HOLD. REL RBP & SET @ 6070'. TEST TO 1000#-NO HOLD. REL RBP & PULL UP TO 5630'. NO HOLD. TOH W/PKR & PLUG.
5-06-98: BLED DN. TIH W/RBP & PKR ON 2 3/8" TBG. SET RBP @ 6019'. SLIPPED DN HLE TO 6030'. PRESS RBP TO 1000#-NO HOLD. LATCH ONTO RBP & REL. RESET PLUG @ 5197'. (ABOVE PERFS) PRESS TO 1000#-NO HOLD. TIH W/MILCOR RBP & PKR. SET RBP @ 6216'. TEST TO 1000#-NO HOLD. DROPPED SV & PRESS TBG TO 1000#-OK. FSH SV & TOH W/TBG, PKR & RBP. SLIPS ON RBP FULL OF HARD SCALE. TIH W/RBP & PKR & SN ON 2 3/8" TBG. SET RBP @ 6010'. PULL 1 JT & SET PKR @ 5983'. TEST RBP TO 1000#-OK. PULL UP & PSA 5670'. LOAD & TEST BACKSIDE TO 500# W/90 BBLS 2% KCL-OK. ACIDIZE 5772-5896' W/3500 GALS 15% NEFE HCL & 2000# RK SLT. PMPD IN 3 STGS.
5-07-98: BLED TBG DN. REL PKR & TIH TO RBP @ 6010'. REL RBP. TIH W/MA, SUB, SN, & 2 3/8" TBG. MA @ 6797'. SN @ 6767'. TAC @ 6448'. NDBOP. SET TAC. NUWH. TIH W/GAS ANCHOR, PMP, ROD GUIDE, & SUBS. LOAD & TEST -OK. CHECK PMP ACTION-OK. RIG DOWN.
5-19-98: ON 24 HR OPT. PUMPED 0 BO, 48 BW, & 397 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 5/20/98

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS DISTRICT I SUPERVISOR

APPROVED BY CHRIS WILLIAMS TITLE DISTRICT I SUPERVISOR DATE OCT 16 1998

CONDITIONS OF APPROVAL, IF ANY: