

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06074
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name C. H. Weir "A"
8. Well No. 8
9. Pool name or Wildcat Skaggs, Weir, Monument <i>Leona, Abby, Sub 1</i>
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
Texaco Producing Inc.

3. Address of Operator  
P. O. Box 730, Hobbs, New Mexico 88240

4. Well Location  
Unit Letter F : 1980 Feet From The West Line and 1985 Feet From The North Line

Section 12 Township 20S Range 37E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU 10-5-88.
- Established circulation down Blinebry (West) string and back up Tubb string (East). Pump 500 Sxs Class H Cmt. down Blinebry string. Circulated 4 sxs out of Tubb string.
- TIH in Glorieta string with tubing. Spotted 2 sxs cement on top of CIBP from 5275-5075. Spot 9 sxs plug from 3950' - 3650'. Spotted 9 sxs plug from 2700' - 2400'. Spotted 9 sxs plug from 1650' - 1350'. Spotted surface plug from 100' to surface.
- RDPU. Installed dry hole marker 10-7-88.

Plugging witnessed by R.A. Sadler with NMOCD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. A. Head TITLE Area Manager DATE 04-05-90

TYPE OR PRINT NAME J. A. Head TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY R. A. Sadler TITLE OIL & GAS INSPECTOR DATE APR 13 1990

CONDITIONS OF APPROVAL, IF ANY: