

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator TEXACO INC.		8. Farm or Lease Name C. H. Weir A
3. Address of Operator P.O. BOX 728 Hobbs, NM 88240		9. Well No. 8
4. Location of Well UNIT LETTER <u>F</u> , <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>1985</u> FEET FROM THE <u>North</u> LINE, SECTION <u>12</u> TOWNSHIP <u>20-S</u> RANGE <u>37-E</u> NMPM.		10. Field and Pool, or Wildcat See below
15. Elevation (Show whether DF, RT, GR, etc.) 3574' (DF)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Repair Water Flow</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

Field - Skaggs Glorieta, Weir Blinebry East, Monument Tubb

1. RIGGED UP. PULL RODS AND PUMP FROM GLORIETA STRING. PULL 2 1/16" TUBING AND PACKER FROM MONUMENT STRING.
2. SET CIBP IN TUBB STRING @ 4000' AND SPOT 40' CEMENT O N TOP OF PLUG.
3. SET CIBP IN GLORIETA @ 3994' AND SPOT 40' CEMENT ON PLUG.
4. SET CIBP IN BLINEBRY @ 4020' AND SPOT 40' CEMENT ON PLUG.
5. PERFORATE 2 7/8" TUBB STRING W/ 2-JS @ 1489'.
6. CEMENT 2 7/8" CSG PERFS @ 1489' W/ 500 SX CLASS H CEMENT CONTAINING 2% CACL. CEMENT CIRCULATED. SQUEEZE W/ ADDL 240 SX CLASS H CEMENT. WOC. DOC.
7. TESTED CASING TO 700# FOR 30 MINUTES, 2:00 - 2:30 PM, 10-17-83. TESTED OK.
8. INSTALL PUMPING EQUIPMENT IN GLORIETA STRING.
9. DOC & CIBP IN TUBB AND BLINEBRY STRINGS.
10. INSTALL PRODUCTION EQUIPMENT. TEST AND RETURN TO PRODUCTION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst Dist Mgr DATE 11-11-83

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT 1 SUPERVISOR DATE NOV 16 1983  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 15 1983

O.C.D.  
HOBBS OFFICE