

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- <input checked="" type="checkbox"/> Water Injection	7. Unit Agreement Name Skaggs Grayburg Unit
Name of Operator TEXACO Inc.			8. Farm or Lease Name Skaggs Grayburg Unit
Address of Operator P. O. Box 728, Hobbs, New Mexico 88240			9. Well No. 7
Location of Well UNIT LETTER 0 1977 FEET FROM THE East LINE AND 661 FEET FROM THE South LINE, SECTION 12 TOWNSHIP 20-S RANGE 37-E NMPM.			10. Field and Pool, or Wildcat Skaggs Grayburg
15. Elevation (Show whether DF, RT, GR, etc.) 3563' (DF)			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:


PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
NULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIG UP. INSTALL BOP. PULL TUBING AND PACKER.
2. SET CIBP @ 3750' (OR AS DEEP AS POSSIBLE) AND SPOT 200' CEMENT (30 SXS) ON TOP OF PLUG.
3. SPOT 30 SX CEMENT PLUG FROM 3300-3100'.
4. SPOT 15 SX CEMENT PLUG FROM 2650-2550'.
5. SPOT 15 SX CEMENT PLUG FROM 1500-1400'.
6. SPOT 10 SX CEMENT PLUG @ SURFACE.
7. INSTALL DRY HOLE MARKER. CLEAN LOCATION. PLUG AND ABANDON WELL.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-102 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Asst. Dist. Mgr.	DATE 10-3-84
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR	TITLE	DATE OCT - 5 1984

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY: