

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <u>CONTINENTAL Oil Company</u>	8. Farm or Lease Name <u>STATE C-16</u>
3. Address of Operator <u>Box 460 Hobbs, NM. 88240</u>	9. Well No. <u>2</u>
4. Location of Well UNIT LETTER <u>E</u> <u>2310</u> FEET FROM THE <u>NORTH</u> LINE AND <u>330</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>16</u> TOWNSHIP <u>20 S</u> RANGE <u>37 E</u> NMPM.	10. Field and Pool, or Wildcat <u>GRAYBURG</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3539' DF</u>	12. County <u>LEA</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <u>AND CMT SQZ. CSG LK.</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WORK DONE ON SUBJECT WELL AS FOLLOWS:

- RIG UP, pull prod. eqpt., GO IN HOLE w/ 6 1/8" bit, C.O. to T.D.,
- BIT STUCK @ 540', FISHED FOR & RECOVER'D BIT., FND CSG LK @ 574'
- SQUEEZE 100 SX CLASS C CMT, displaced CMT below sqz. tool, press. to 1000 psi. (O.K.)
- PERF @ 3675'-77', 3517'-20', 24', 27', 3534' w/ 2 JSPP. PERF. OH SECTION @ 3748', 51, 54, 57, 60, 3763'. Acidize OH PERFS w/ 500 gals 15% NEMCL ACID
- ACIDIZE CSG PERFS 3675-77 w/ 500 gals 15% NE-HCL ACID.
- ACIDIZE CSG PERFS 3517-34 w/ 1000 gals
- WORK. UNSUCCESSFUL.
- SHUT WELL IN.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bernard L. Lee TITLE Admin. Supr DATE 8-16-78

APPROVED BY Jerry Sexton DATE 8/21/79

CONDITIONS OF APPROVAL, IF ANY: none sat file Expires 8/21/79