

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

3-MOCC
1-File

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name STATE I
9. Well No. 2
10. Field and Pool, or Wildcat MONUMENT GRAYBURG
12. County LEA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator GETTY OIL COMPANY
3. Address of Operator P.O. BOX 249, HOBBS, NEW MEXICO 88240
4. Location of Well UNIT LETTER K, 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 16 TOWNSHIP 20-S RANGE 37-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3541 D.F.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

It is proposed to re-enter this temporarily abandoned well, and test the Paddock zone as follows.

Drill out surface plug and plug at 3502-33'. Perforate Paddock 5178-88' with 11 shots. Run treating packer and swab test, treat with HCL acid if necessary. If test is salt water, squeeze perforations with cement. If test is oil, additionally perforate Paddock with one SPF 5124-32; 5124-46; and 5154-60'. Swab test. Acidize with approximately 2,000 Gal. HCL, if necessary.

Depending on the outcome of the test, the Grayburg-San Andres will be squeezed off or a separating packer run to separate the two zones.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. L. Wade	TITLE AREA SUPERINTENDENT	DATE 11-26-73
APPROVED BY Orig. Signed by John E. Ryan C. L. Wade	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		

WLG/hh