

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee.....
Lease No.....

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF WATER SHUT-OFF ACIDIZING..... X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

P.P. Co.
Hobbs No. 2

June 14, 1937

Well No. 2 is located 1980 ft. from XX line and 660 ft. from XX line of sec. 18

SW/4, Sec. 18 20-S 37-E N. M. P. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Monument Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3573 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth 3865 line. Treated pay formations from 3767 to 3865 with 4000 gallons Dowell "XX" solution through tubing. Treated June 9, 1937, by Dowell Inc. Second treatment. Started flowing after swabbing 50 barrels oil load and acid. Flowed 100 bbl. in one hour which finished recovering oil load. Next hour flowed 91 barrels oil on gas lift. Discontinued high pressure gas. First 30 minutes flowed 20-1/2 barrels oil. Next 30 minutes flowed 42 barrels oil, no water and shut in for tank room. Gas measured 900,000. Next day flowed 329 barrels oil, no water, natural on 5 hour test. Gas measured 1,200,000. Following day flowed 505 barrels oil, no water in 10 hours natural through tubing. Gas measured 1,250,000'.

Well dead before acidizing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum Company

Address Box 1390, Midland, Texas

By /s/ Earl Griffin

Title District Superintendent

UNRECORDED COPY
UNRECORDED COPY
UNRECORDED COPY
UNRECORDED COPY
UNRECORDED COPY

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED