

Indian Agency.....

(SUBMIT IN TRIPLICATE)

U. S. Land Office Las Cruces, N. M.Lease or permit No. 031621-B

Allottee.....

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Lease No.....

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL..... NOTICE OF INTENTION TO CHANGE PLANS..... NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... NOTICE OF INTENTION TO PULL OR ALTER CASING..... NOTICE OF INTENTION TO ABANDON WELL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF..... SUBSEQUENT REPORT OF <del>WATER SHUT-OFF</del> ACIDIZING..... <b>X</b> SUBSEQUENT REPORT OF ALTERING CASING..... SUBSEQUENT REPORT OF REDRILLING OR REPAIR..... SUBSEQUENT REPORT OF ABANDONMENT..... SUPPLEMENTARY WELL HISTORY.....
---	---

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

P.P. Co.  
Hobbs #2

June 9, 1937

Well No. Two is located 1980 ft. from XX line and 660 ft. from W line of sec. 18

SW/4, Section 18      20-S      37-E      N. M. P. M.  
(1/4 Sec. and Sec. No.)      (Twp.)      (Range)      (Meridian)  
Monument      Lea      New Mexico  
(Field)      (County or Subdivision)      (State or Territory)

The elevation of the derrick floor above sea level is 3573 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth 3865 in lime. Treated pay formations from 3767 to 3865 with 1000 gallons Dowell "XX" solution. Treated June 8, 1937, by Dowell Inc.

Let set one hour after treating and applied high pressure gas through annular space and flowed out 100 barrels oil load and acid and started swabbing. Ran swab four times and well started unloading again and flowed 100 barrels oil load and acid. Hole completely unloaded. Let set over night. Opened this morning. Flowed 11 barrels fresh oil in one hour and died.

Well dead before acidizing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum Company

Address Box 1390, Midland, Texas

By /s/ Earl Griffin

Title District Superintendent

100-10000

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

WATER RESOURCES DIVISION

REPORT OF THE  
COMMISSIONER OF THE  
GEOLOGICAL SURVEY  
ON THE  
WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900

WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900

WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900

WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900

WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900

WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900

WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900

WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900

WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900

WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900

WATER RESOURCES OF THE  
UNITED STATES  
FOR THE YEAR  
1900