

Allottee

Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Phillips Petroleum Co.,
Hobbs No. 4

Okla., Twp. 20-3, Range 27-2, Meridian N.M.P.M., June 25, 1939

Well No. **4** is located **600** ft. from **S** line and **2000** ft. from **E** line of sec. **10**

SW/4 Sec. 10
(1/4 Sec. and Sec. No.)

20-3
(Twp.)

27-2
(Range)

N.M.P.M.
(Meridian)

DUPLICATE

Monument
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **5344.7** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T.D. 3745 Line. Tested 7" casing for water shut-off with 1200' water pressure before and after drilling cement plug.
Water shut-off satisfactory.

RECEIVED
JUN 26 1939
RECEIVED
HOBBS OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Phillips Petroleum Company**

Address **Drewes Bldg., Okla., Hobbs**

By

Carl G. ...
Title **District Superintendent.**

Las Cruces, N.M.
1-13-31-0

(RECEIVED IN THE BUREAU)

RECEIVED
JAN 14 1931

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OFFICE OF THE ASSISTANT ATTORNEY GENERAL
WASHINGTON, D. C.

TO THE SECRETARY OF THE INTERIOR
FROM THE ATTORNEY GENERAL
SUBJECT: [Illegible]

[The following text is extremely faint and largely illegible due to the quality of the scan. It appears to be a memorandum or letter containing several paragraphs of text, possibly discussing land management or legal matters.]