

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Eunice Monument Unit
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name Eunice Monument Unit
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 23
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>19</u> TOWNSHIP <u>20-S</u> RANGE <u>37-E</u> NMPM.	10. Field and P. No., or Wildcat Eunice Monument Grayburg - San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3533' (DF)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIG UP. INSTALL BOP.
2. SPOT 25 SX. CEMENT PLUG FROM 3720' - 3507'.
3. SPOT 50 SX. CEMENT PLUG FROM 3348' - 2950'.
4. CUT 5 1/2" CASING @ 2245'. PIPE STUCK @ 1250'.
5. SPOT 50 SX. CEMENT PLUG FROM 2068' - 1250'.
6. CUT 5 1/2" CASING @ 1250' AND PULLED SAME.
7. SPOT 35 SX. CEMENT PLUG FROM 1271' - 1152'.
8. CUT 8 5/8" CASING @ 810' AND PULLED SAME.
9. SPOT 50 SX. CEMENT PLUG FROM 850' - 680'.
10. SPOT 50 SX. CEMENT PLUG FROM 347' - 221'.
11. SPOT 75 SX. CEMENT PLUG FROM 75' - SURFACE.
12. INSTALL DRY HOLE MARKER. CLEAN LOCATION. WELL PLUGGED AND ABANDONED 7-13-83.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst Dist Mgr DATE 9-2-83

APPROVED BY [Signature] TITLE DATE POT 11 1983

CONDITIONS OF APPROVAL, IF ANY: