Submit 5 Copies
Appropriate District Office
DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

State of New Mexico Minerals and Natural Resources Department

Form C-104 Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410

REQUEST FOR ALLOWABLE AND AUTHORIZATION

[,	T	OTRAN	SPORT OIL	AND NAT	URAL GA	S	MINT.		
Operator Texaco Exploration and Pr	oduction in	ic.				30 (025 06180)	DK
Address		00040	0500						
P. O. Box 730 Hobbs, N Reason(s) for Filing (Check proper box, New Well Recompletion Change in Operator		Change in Tr			t (Please expla FECTIVE 6-				
	aco Produ	cing inc.	P. O. Bo	x 730 I	lobbs, Nev	w Mexico	88240-2	528	
II. DESCRIPTION OF WELL Lease Name	[Well No. Po	ool Name, Includi UMONT YATI		ON (DDO G	State.	of Lease Federal or Fee		ease No. 30
NEW MEXICO H STATE NO Location	1 4							MEGT	
Unit LetterL	:1653	F	eet From The SC	UTH Lin	and969	Fe	et From The	WEST	Line
Section 19 Town			ange 37E		иРМ,	<u> </u>	LEA		County
III. DESIGNATION OF TRA Name of Authorized Transporter of Oil	NSPORTEI	or Condensat	AND NATU	RAL GAS Address (Giv	e address to wh	ick approved	copy of this fo	orm is to be se	ni)
Name of Authorized Transporter of Car Texaco Exploration	singhead Gas n and Prode		r Dry Gas X		e address to wh O. Box 11				
If well produces oil or liquids, give location of tanks.	Unit	Sec. T	wp. Rge.	<u> </u>	YES	When	-	KNOWN	
If this production is commingled with the IV. COMPLETION DATA	at from any oth	er lease or po	oi, give comming		. 		······································		
Designate Type of Completic	on - (X)	Oil Well	Gas Well	New Well	Workover 	Deepen	Plug Back	Same Res'v 	Diff Res'v
Date Spudded		i. Ready to P	rod.	Total Depth	<u> </u>		P.B.T.D.		
levations (DF, RKB, RT, GR, etc.) Name of Producing Formation		Top Oil/Gas Pay			Tubing Depth				
Perforations							Depth Casin	g Shoe	
			CASING AND	CEMENTI					
HOLE SIZE	CAS	SING & TUB	ING SIZE		DEPTH SET		<u> </u>	SACKS CEM	ENI
V. TEST DATA AND REQU OIL WELL (Test must be aft	EST FOR A	LLOWAI rial volume of	BLE load oil and mus	t be equal to o	exceed top all	owable for th	is depth or be	for full 24 hou	σs.)
Date First New Oil Run To Tank	Date of Te			Producing M	ethod (Flow, pr	ump, gas lift,	etc.)		
Length of Test	Tubing Pre	Tubing Pressure		Casing Pressure			Choke Size		
Actual Prod. During Test	Oil - Bbls.	Oil - Bbls.		Water - Bbls.		Gaa- MCF			
GAS WELL							10	Candanari	
Actual Prod. Test - MCF/D	Length of	Test		Bbis. Conde	sate/MMCF		Gravity of	Longensale	
Testing Method (pitot, back pr.)	Tubing Pre	Tubing Pressure (Shut-in)			Casing Pressure (Shut-in)		Choke Size		
VI. OPERATOR CERTIF I hereby certify that the rules and rules of the best complied with a strue and complete to the best of t	egulations of the and that the info my knowledge a	Oil Conserve rmation gives	ntion	Date	OIL CON	ed	UN G a	19 91	ON
Signature K. M. Miller			rs. Engr.	By_		3 8 () () ()		100	
Printed Name May 7, 1991		915-6	88-4834 hone No.	Title)		 		

INSTRUCTIONS: This form is to be filed in compliance with Rule 1104

- 1) Request for allowable for newly drilled or deepened well must be accompanied by tabulation of deviation tests taken in accordance with Rule 111.
- 2) All sections of this form must be filled out for allowable on new and recompleted wells.
- 3) Fill out only Sections I, II, III, and VI for changes of operator, well name or number, transporter, or other such changes.
- 4) Separate Form C-104 must be filed for each pool in multiply completed wells.







Job separation sheet

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy nerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

OIL C	CONSER	VATION	DIVISION
	P.O	. Box 2088	

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06180

DISTRICT III	STATE X FEE
000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.
OOU RAD BIRRAR RAIN, PLANS VINTA	B-160
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	
. Type of Well:	
ORT OTHER	New Mexico "H" State NCT-4
Name of Operator	8. Well No.
Texaco Producing Inc.	27
Address of Operator	9. Pool name or Wildcat
P. O. Box 730 Hobbs, NM 88240	Eumont Yates 7 Rvrs Qn
4. Well Location	
Unit Letter L : 1653 Feet From The South Line and 96	Feet From The West Line
Section 19 Township 20S Range 37E	NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
//////////////////////////////////////	
11. Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data
NOTICE OF INTENTION TO:	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	XX ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	ING OPNS. DPLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND	CEMENT JOB
OTHER: OTHER:	
	ncluding estimated date of starting any proposed
1. MIRU. Pld rods & pmp. Lowered tbg. 2. TIH w/ pkr. Set @ 3317. Attempted to 3. Set RBP @ 3300'. Tstd RBP to 1000#. 784'-3300' at 1000#. Held OK. Locat Est Rate @ 3 BPM with full circulatio 4. Ran free point, found 5-1/2" free at off at 824'. POH. 5. TIH w 27 jts 5-1/2" csg, screw onto f Cut off csg. Installed wellhead. Tes 6. Retrieved RBP. TIH w/ pkr. Set @ 32 to 500#. OK. 7. Acidized Eumont OH (3358-3550) w/ 300 Max Press = 2040#. AVIR = 8 BPM. 8. Frac Eumont w/ 23950 gal 40# linear g 187240# 12/20 sand. Max Press = 3629 9. Flowed back 5 hrs. Well died. 10. POH w/ pkr. TIH w/ bit. Tagged fill to 3525'. POH. Ran tbg, rods, pump. 11. OPT 9-9-90 0 BOPD, 18 EWPD, 496 MCFD.	Tag fill @ 3527. POH. load casing. Had leak. OK. Tested from ed leak @ 752'. n out of 8-5/8". l150'. Backed 5-1/2" ish. Tstd to 500#. OK. ted to 1500#. OK. 85'. Load & test csg 0 gal 15% NEFE. el, 23950 gal CO2 & #. AVIR = 30 BPM. @ 3358'. Cleaned out
2. TIH w/ pkr. Set @ 3317. Attempted to 3. Set RBP @ 3300'. Tstd RBP to 1000#. 784'-3300' at 1000#. Held OK. Locat Est Rate @ 3 BPM with full circulatio 4. Ran free point, found 5-1/2" free at off at 824'. POH. 5. TIH w 27 jts 5-1/2" csg, screw onto f Cut off csg. Installed wellhead. Tes 6. Retrieved RBP. TIH w/ pkr. Set @ 32 to 500#. OK. 7. Acidized Bumont OH (3358-3550) w/ 300 Max Press = 2040#. AVIR = 8 BPM. 8. Frac Eumont w/ 23950 gal 40# linear g 187240# 12/20 sand. Max Press = 3629 9. Flowed back 5 hrs. Well died. 10. POH w/ pkr. TIH w/ bit. Tagged fill to 3525'. POH. Ran tbg, rods, pump. 11. OPT 9-9-90 0 BOPD, 18 BWPD, 496 MCFD.	Tag fill @ 3527. POH. load casing. Had leak. OK. Tested from ed leak @ 752'. n out of 8-5/8". l150'. Backed 5-1/2" ish. Tstd to 500#. OK. ted to 1500#. OK. 85'. Load & test csg ogal 15% NEFE. gel, 23950 gal CO2 & lf. AVIR = 30 BPM. @ 3358'. Cleaned out
2. TIH w/ pkr. Set @ 3317. Attempted to 3. Set RBP @ 3300'. Tstd RBP to 1000#. 784'-3300' at 1000#. Held OK. Locat Est Rate @ 3 BPM with full circulatio 4. Ran free point, found 5-1/2" free at off at 824'. POH. 5. TIH w 27 jts 5-1/2" csg, screw onto f Cut off csg. Installed wellhead. Tes 6. Retrieved RBP. TIH w/ pkr. Set @ 32 to 500#. OK. 7. Acidized Eumont OH (3358-3550) w/ 300 Max Press = 2040#. AVIR = 8 BPM. 8. Frac Eumont w/ 23950 gal 40# linear g 187240# 12/20 sand. Max Press = 3629 9. Flowed back 5 hrs. Well died. 10. POH w/ pkr. TIH w/ bit. Tagged fill to 3525'. POH. Ran tbg, rods, pump. 11. OPT 9-9-90 0 BOPD, 18 BWPD, 496 MCFD. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SMONATURE TIME Engineer's	Tag fill @ 3527. POH. load casing. Had leak. OK. Tested from ed leak @ 752'. n out of 8-5/8". l150'. Backed 5-1/2" ish. Tstd to 500#. OK. ted to 1500#. OK. 85'. Load & test csg 0 gal 15% NEFE. el, 23950 gal CO2 & lf. AVIR = 30 BPM. @ 3358'. Cleaned out
2. TIH w/ pkr. Set @ 3317. Attempted to 3. Set RBP @ 3300'. Tstd RBP to 1000#. 784'-3300' at 1000#. Held OK. Locat Est Rate @ 3 BPM with full circulatio 4. Ran free point, found 5-1/2" free at off at 824'. POH. 5. TIH w 27 jts 5-1/2" csg, screw onto f Cut off csg. Installed wellhead. Tes 6. Retrieved RBP. TIH w/ pkr. Set @ 32 to 500#. OK. 7. Acidized Bumont OH (3358-3550) w/ 300 Max Press = 2040#. AVIR = 8 BPM. 8. Frac Eumont w/ 23950 gal 40# linear g 187240# 12/20 sand. Max Press = 3629 9. Flowed back 5 hrs. Well died. 10. POH w/ pkr. TIH w/ bit. Tagged fill to 3525'. POH. Ran tbg, rods, pump. 11. OPT 9-9-90 0 BOPD, 18 BWPD, 496 MCFD.	Tag fill @ 3527. POH. load casing. Had leak. OK. Tested from ed leak @ 752'. n out of 8-5/8". l150'. Backed 5-1/2" ish. Tstd to 500#. OK. ted to 1500#. OK. 85'. Load & test csg ogal 15% NEFE. gel, 23950 gal CO2 & lf. AVIR = 30 BPM. @ 3358'. Cleaned out
2. TIH w/ pkr. Set @ 3317. Attempted to 3. Set RBP @ 3300'. Tstd RBP to 1000#. 784'-3300' at 1000#. Held OK. Locat Est Rate @ 3 BPM with full circulatio 4. Ran free point, found 5-1/2" free at off at 824'. POH. 5. TIH w 27 jts 5-1/2" csg, screw onto f Cut off csg. Installed wellhead. Tes 6. Retrieved RBP. TIH w/ pkr. Set @ 32 to 500#. OK. 7. Acidized Eumont OH (3358-3550) w/ 300 Max Press = 2040#. AVIR = 8 BPM. 8. Frac Eumont w/ 23950 gal 40# linear g 187240# 12/20 sand. Max Press = 3629 9. Flowed back 5 hrs. Well died. 10. POH w/ pkr. TIH w/ bit. Tagged fill to 3525'. POH. Ran tbg, rods, pump. 11. OPT 9-9-90 O BOPD, 18 BWPD, 496 MCFD. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TYPE OR FRINT NAME L. D. Ridenour	Tag fill @ 3527. POH. load casing. Had leak. OK. Tested from ed leak @ 752'. n out of 8-5/8". l150'. Backed 5-1/2" ish. Tstd to 500#. OK. ted to 1500#. OK. 85'. Load & test csg 0 gal 15% NEFE. el, 23950 gal CO2 & lf. AVIR = 30 BPM. @ 3358'. Cleaned out
2. TIH w/ pkr. Set @ 3317. Attempted to 3. Set RBP @ 3300'. Tstd RBP to 1000#. 784'-3300' at 1000#. Held OK. Locat Est Rate @ 3 BPM with full circulatio 4. Ran free point, found 5-1/2" free at off at 824'. POH. 5. TIH w 27 jts 5-1/2" csg, screw onto f Cut off csg. Installed wellhead. Tes 6. Retrieved RBP. TIH w/ pkr. Set @ 32 to 500#. OK. 7. Acidized Eumont OH (3358-3550) w/ 300 Max Press = 2040#. AVIR = 8 BPM. 8. Frac Eumont w/ 23950 gal 40# linear g 187240# 12/20 sand. Max Press = 3629 9. Flowed back 5 hrs. Well died. 10. POH w/ pkr. TIH w/ bit. Tagged fill to 3525'. POH. Ran tbg, rods, pump. 11. OPT 9-9-90 0 BOPD, 18 BWPD, 496 MCFD. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SKONATURE TITLE Engineer's	Tag fill @ 3527. POH. load casing. Had leak. OK. Tested from ed leak @ 752'. n out of 8-5/8". l150'. Backed 5-1/2" ish. Tstd to 500#. OK. ted to 1500#. OK. 85'. Load & test csg 0 gal 15% NEFE. el, 23950 gal CO2 & lf. AVIR = 30 BPM. @ 3358'. Cleaned out