\square	UPEHCAT	Γ
IJ		L

CO	OIL	CONSERVATION	COMM

RECEIVE

MAY - 2 1951

SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is the seder on which will be given the approval, with any modified to the seder on which will be given the approval, with any modified to the seder of a dvisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed and work should not begin until approval is obtained. See additional instructions in the Reles and Gestations the Commission.

Indicate nature of notice by checking below:

Midland, To	exas	April 27 , 1951	
NOTICE OF INTENTION TO DEEPEN WELL			
NOTICE OF INTENTION TO REPAIR WELL	x	NOTICE OF INTENTION TO PLUG WELL	
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO TEST CASING SHUT-OFF		NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	

OIL CONSERVATION COMMISSION,

Santa Fe, New Mexico

Gentlemen:

Following is a notice	of intention to	do certain work as des	ribed below at the The Te	xas company
Following is a notice	State	of New Mexico	"H" (Lieu)	N_{No} 6 $NW/4$ NE/4
Company or Operato	r	Lease	•	
20	20 8		Manager and	

of Sec. 20, T. 20-5, R. 37-E., N. M. P. M., MONUMENT. Field.

Lea County.

NEW

FULL DETAILS OF PROPOSED PLAN OF WORK

FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

TD: 3860'-Lime

On production test ending 1-15-51, well pumped 19 bbls oil and 274 bbls water in 24 hrs, There has been no remedial work done on this well since its completion on 3-27-37.

We desire to enter well and set cement retainer @ 3775. Load open hole above retainer and seal if necessary. Squeeze open hole below retainer with 250 sacks cement with 1/4 # Flocele added per sack. Wash cement out to top of retainer and pull tubing. Re-run tubing, swab and test, Acidize with 500 gallon acid if necessary, using 5 gallons heavy aquagel slurry for blanket. Swab, test, and return well to pumping status.

Company
Company or Operator
st. Supt.
mmunications regarding well to
exas Company
1270
and, Texas