

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-66

5a. Indicate Type of Lease  
State NEW MEXICO ☐  
5. State Oil & Gas Lease No.  
B-160

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name <u>None</u>
2. Name of Operator <u>TEXACO Inc.</u>	8. Farm or Lease Name <u>New Mexico "H" State</u>
3. Address of Operator <u>P. O. Box 728, Hobbs, New Mexico 88240</u>	9. Well No. <u>16</u>
4. Location of Well UNIT LETTER <u>K</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> <u>20</u> TOWNSHIP <u>20-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Eunice Grayburg San Andres</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TEXACO HAS COMPLETED THE FOLLOWING WORK ON SUBJECT WELL:

1. Shut well in 24 hours.
2. Pumped mixture of 110 gals. Bariod H-35 W/400# KOH, 10 Gal. Sure-Flo S-32, 10 barrels fresh water down well.
3. Flush W/20 barrels lease crude.
4. Allow mixture to set and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Assistant District Superintendent</u>	DATE <u>April 22, 1969</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR</u>	DATE <u>April 22, 1969</u>
CONDITIONS OF APPROVAL, IF ANY:		