

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐ 5. State Oil & Gas Lease No. B-160
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-	7. Unit Agreement Name Eunice Monument Unit	
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name Eunice Monument Unit	
3. Address of Operator P.O. Box 728 Hobbs, New Mexico 88240	9. Well No. 8	
4. Location of Well UNIT LETTER A 330 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 20 TOWNSHIP 20-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Eunice Monument Grayburg San Andres	
15. Elevation (Show whether DF, RT, GR, etc.) 3526' (GR)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pulled rods and pump. Install BOP. Pull tubing.
2. Set RBP @ 3578'. Log Well.
3. Perforate 7" csg w/4-JS @ 1490'.
4. Set cement retainer @ 1452'. Squeeze 7" csg. perforation 1490' w/100 bbls Howco Flo-ck gel followed w/300 sx Class C cement cont 3% CaCl. PBTD 1441'.
5. Perforate 7" csg w/2-JSPF @ 1175' & 1177'.
6. Set cement retainer @ 1151'. Squeeze 7" csg perforations 1175' & 1177' w/283 sx Class C cement containing 6% CaCl.
7. DOC and retainer and clean out to 1493' (PBTD). Set cement retainer at 1490' and pump 70 bbls. 10# brine @ 4 BPM & 1000#. Follow w/100 bbls Flo-Check. Pump 300 bbls Class C sement. Did not squeeze. Clear perfs w/5 bbls fresh water.
8. Squeeze 7" csg perf @ 1490' w/100 sx Class C cement containing 2% CaCl followed w/100 sx 60-40 Class 'H' Cement.
9. Clean out to 3857' (TD).
10. Install pumping equipment. Test and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 6-1-77

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: