ISGY AND MINERALS DEPARTMENT	
C _ CONSERVATION DIVISION	
DISTRIBUTION     P. O. BOX 2088	_
	Form C-103 . Revised 10-1-78
SANTA FE, NEW MEXICO 87501	
U.3.d.s,	Sa. Indicate Type of Lease
OPERATOR .	State X Foo
<u>orca, or</u>	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
SIL GAS WELL OTHER-INJECTOR	7. Unit Agreement Name
me at Operator	EUNICE MONUMENT SOUTH UN
Chevron U.S.A. Inc.	8. Fam or Lease Name
D. O. Dow 272 Half and	9. Weil No.
P.O. Box 670 Hobbs, NM 88240	174
cation of Well	10. Field and Pool, or Wildcat
UNIT LETTER M . 330 FEET FROM THE SOUTH LINE AND 330 FEET FROM	4
	EUNICE MONUMENT G/SA
THE WEST LINE, SECTION 32 TOWNSHIP 205 RANCE 37E	
15. Elevation (Show whether DF, RT, GR, etc.)	
3550. GL	12. County -
Check Appropriate Box To Indicate Nature of Notice, Report of Ot	LEA (IIIIII
NOTICE OF INTENTION TO: SUBSEQUEN	REPORT OF:
PLUC AND ABANDON ACMEDIAL WORK	ALTERING CASING
COUMCHEE DRILLING OPHS.	PLUG AND ABANDONMENT
OR ALTER CASING TEST AND CEMENT JOS	
CONVERT TO INJECTOR	
THES CONVERT TO INDECTOR	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including pork) SEZ RULE 1703.	
with SEZ RULE 1103.	estimated date of starting any proposed
Clean out to TD @ $3860$ . Log well. Add additional Grayburg point indicate. Acidize as necessary. Equip for injection. Test casing 600 psi. for 30 minutes. Return to production as an injector.	erforations as logs , packer, and tubing to
• • •	

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

TITLE

Staff Drilling Engineer

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

TITLE

MAR 1 1 1987