	-	B	ludget Bureau No. 42-R Approval expires 12-31-6	1358.4 . 0.
Form 5-831 a (Feb. 1961)	(SUBMIT IN TRIPLICATE) UNITED STATES	Land Office 0 31736 (b) Unit		
	DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	
NOTICE OF INTENTION TO PULL OR ALTER CASING	
NOTICE OF INTENTION TO ABANDON WELL	

O.J. Gillully "B"	November 16,			. 19 59	
Well No. <u>4</u> is located	340 ft.	from $\begin{bmatrix} N \\ K \end{bmatrix}$ line	and 340 ft. from		. 22
NW/4 NW/4 Sec. 22	T-20-5	R-37-E	NMPM	• •	
(14 Bec. and Sec. No.)	(Twp.)	(Range)	(Meridian) NGN	n Mexáco	
(Field)	(Co	unty or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is 3554 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

This repair was authorized on Form 9331a submitted 10-30-59. The following work was done and packer leak eliminated.

- 1. Pulled tubing and upper packer
- 2. Bridge plug set at 36951 and capped with 51 cement.
- 3. Perforated 36391-481; 36601-691, with tubing gun. Hodel D Packer set at 36001.
- 4. Acidised with 1000 gal. 15% regular.
- 5. Put well on production.

Monument zone tested 860 MCFGPD, no water. MPF 175, 36/64" choke Eumont zone cleaned up. No change in status.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company	Pan American Petroleum Corporation					
	P. O. Box 68					
	Hobbs	By <u>1 and 1 and</u>				
	New Next.co	Title Area Superintendent				

GPO 862040