

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions  
verse side)

Budget Bureau No. 1004-0133  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

|                                                                                                                                                       |                                                                            |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> <u>temp. Shut-in</u>                 | 5. LEASE DESIGNATION AND SERIAL NO.<br><u>LC-031670(A)</u>                 |
| 2. NAME OF OPERATOR<br><u>CONOCO INC.</u>                                                                                                             | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME<br><u>LC-031696-A</u>                 |
| 3. ADDRESS OF OPERATOR<br><u>P. O. Box 460, Hobbs, N.M. 88240</u>                                                                                     | 7. UNIT AGREEMENT NAME                                                     |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface <u>Unit I</u> | 8. FARM OR LEASE NAME<br><u>SEMU Meyer</u>                                 |
| 14. PERMIT NO.<br><u>3C-025-06261</u>                                                                                                                 | 9. WELL NO.<br><u>82</u>                                                   |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)                                                                                                        | 10. FIELD AND POOL, OR WILDCAT<br><u>Blinbry Oil &amp; Gas</u>             |
|                                                                                                                                                       | 11. SEC., T., E., N., OR BLK. AND SURVEY OR AREA<br><u>Sec. 25-20S-37E</u> |
|                                                                                                                                                       | 12. COUNTY OR PARISH<br><u>Lea</u>                                         |
|                                                                                                                                                       | 13. STATE<br><u>NM</u>                                                     |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- ① MURU, POOH w/ tbg. Run csq scraper to 5750' and set CIBP @ 5735'. Reverse circ. hole completely w/ 25 sxs gel/100 bbls 9.0 ppg brine wtr.
- ② spot 5 sxs class "C" Neat cmt from 5735'-5685'. Flush to 5681' w/ 22 bbls mud. Spot 10 sxs class "C" Neat from 4100'-4000'.
- ③ Spot 22 sxs Class "C" Neat from 3658'-3558'. Spot 33 sxs Class "C" Neat from 2600'-2500'.
- ④ Perf @ 1350' w/ 4 JSPP. Set cmt retainer @ 1330'. Sting into retainer @ 1330' and pump 500 sxs Class "C" Neat cmt. Circ. cmt to surface 80' em on C.R.
- ⑤ Spot 33 sxs Class "C" Neat from 400'-300'. WOC for 3 hrs. Tag TOC w/ tbg.
- ⑥ Spot 16 sxs Class "C" Neat from 50' to surface. Cut off well head and install P&A marker. Rig down.
- ⑦ A proposed P&A sketch is attached.

18. I hereby certify that the foregoing is true and correct

SIGNED John L. Vogel

TITLE Administrative Supervisor

DATE 7-28-86

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

8-6-86

\*See Instructions on Reverse Side


# SEMU No. 82

Elevation: 3515' GL

"Zero": 16' AGL

1980' FSL 4990' FSL

Sec 25, T-20S, R-37E



Conoco Inc.  
Calculation Sheet

Made By: JWM

Disc: 800

Date: 7-15-86

Page: 1

Job No. \_\_\_\_\_

Field \_\_\_\_\_

State \_\_\_\_\_

The Proposed Condition