

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER: Injector
Name of Operator: Chevron U.S.A. Inc.
Address of Operator: P.O. Box 670, Hobbs, NM 88240
Location of Well:
UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 30 TOWNSHIP 20S RANGE 37E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3540
12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

REFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
LE OR ALTER CASING ☐
OTHER ☐
PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER dpr, log, perf, acidz ☒
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POOH w/production equip. Cleanout f/3817 to 3835. Drill f/3835 to 3915, circulate hole clean w/foam mist. Circulate clean. Log w/ CNL/CCL/GR and caliper. Set pkr at 3545, test tubing to 3000psi, test ann to 600psi, acidize OH 3713-3915 w/6000 gal 15% NEFE HCL, swab, Pressure up old sqz perfs, spot 300 gallons 15% NEFE HCL across perfs., resqueeze perf w/100sx Class C. Tail w/200sx C, stung out w/50bbl into formation. WOC. Drill cmt from 3006 to 3011. Drillout soft cmt to 3015' circulate hole clean. Drill out from 3015 to 3242, circulate clean. Drill cmt f/3242 to 3600, fell through. Tag at 3622. Pressure up and test squeeze, ok. Wash f/3622 - 3648. Circulate clean. RIH w/ 2 3/8 tbg to 3889, and production equipment. Turn over to production. Work performed 9-26-87 through 10-5-87.

TD: 3915

PB: 3915

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. E. Abin

TITLE Staff Drilling Eng.

DATE Oct. 8, 1987

ORIGINAL SIGNED BY JERRY GRAYSON
DISTRICT 1 SUPERVISOR

COPIES BY
NOTATIONS OF APPROVAL, IF ANY:

TITLE

DATE