

3. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEX CO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-1481</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>State F</b>
9. Well No. <b>3</b>
10. Field and Pool, or Without <b>Eunice-Grayburg SA</b>
12. County <b>Lea</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator <b>CITIES SERVICE OIL COMPANY</b>
3. Address of Operator <b>P.O. Box 69, Hobbs, N.M. 38240</b>
4. Location of Well: UNIT LETTER <b>P</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>30</b> TOWNSHIP <b>20S</b> RANGE <b>37E</b> N.M.P.M.
15. Elevation (Show whether DF, RT, GK, etc.) <b>3536 GR</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged and abandoned on 11-24-71 in the following manner:

1. Pulled tubing and bottom hole assembly.
2. Ran tubing open ended to TD and loaded hole with mud laden fluid.
3. Spotted 50 sack cement plug from TD 3838--3588.
4. Shot and pulled approximately 2500' of 7" casing.
5. Set 40 sack cement plug (105') 1/2 in and 1/2 out of 7" casing stub and 9 5/8" casing shoe 2585--2480'.
6. Set 10 sack cement surface plug in top of 9 5/8" from ground level to 30' with a 4" dry hole marker extending 4' above ground to designate a plugged and abandoned well.
7. Location will be cleared of all equipment and debris and your office notified for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_ TITLE **District Admin. Supervisor** DATE **12-3-71**

APPROVED BY *Nathan E. Olegg* TITLE **INSPECTOR** DATE **FEB 23 1972**  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DEC 1971

OIL CONSERVATION  
HOBBS, N. M.