

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
DISTRICT II  
P.O. Drawer Dd, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) <b>30-025-06289</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>002736</b>
7. Lease Name or Unit Agreement Name <b>SUNSHINE STATE</b> <i>CLU</i>
8. Well No. <b>2</b>
9. Pool name or Wildcat <b>EUMONT; YATES-7 RVRS-QUEEN (PRO GAS)</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator <b>CHEVRON U.S.A. INC.</b>
3. Address of Operator <b>P.O. BOX 1150 MIDLAND, TX 79702 ATTN: WENDI KINGSTON</b>
4. Well Location Unit Letter <b>N</b> : <b>660</b> Feet From The <b>SOUTH</b> Line and <b>1980</b> Feet From The <b>WEST</b> Line Section <b>30</b> Township <b>20S</b> Range <b>37E</b> NMPM <b>LEA</b> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3539'</b>

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JCB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU, CLEAN OUT TO PBD @3624'. LOAD BACKSIDE W/2% KCL. FRAC PERFS 3310'-3522'  
W/54,000 GALS 50Q CO2 LINEAR GEL & 192,750 LBS 12/20 SD. PERF F/2964'-3042'.  
ACDZ EACH SET W/150 GALS 15% NEFE. LOAD BACKSIDE W/2% KCL. FRAC PERFS 2964'-3042'  
W/51,500 GALS 50Q CO2 LINEAR GEL & 184,500 LBS 12/20 BRADY SD. RIH W/2 3/8" TBG.  
TURN WELL OVER TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Wendi Kingston* TITLE TECH. ASSISTANT DATE: 09/14/95

TYPE OR PRINT NAME WENDI KINGSTON TELEPHONE NO. (915)687-7826

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE SEP 19 1995

CONDITIONS OF APPROVAL, IF ANY: