

Submit this report in TRIPLICATE to the District Office, Oli Conservation Commission, within 10 days after cdmipleted. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well. result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING	REPORT ON RESULT OF 1EST	REPORT ON
Drilling operations	OF CASING SHUT-OFF	REPAIRING WELL
REPORT ON RESULT	REPORT ON RECOMPLETION	REPORT ON
OF PLUGGING WELL	OPERATION	(Other)

Following is a report on the work done and the results obtained under the heading noted above at the

Humble Oll & Refining Company or Operator)	Lease) (Lease)
Company Unit 4763 & J. P. Jibbins , Well No	7 in the N. 1/4 Nus 1/4 of Sec. 31
T20-S, R37-E, NMPM.,	ol,
The Dates of this work were as follows: 7-22-53 to 7-24-53	

out incorrect words. Notice of intention to do the work (was) (more submitted on Form C-102 on.....7-14-53

and approval of the proposed plan (was) (proposed) obtained.

(Title) f

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Ran and set Baker Hodel K cast iron bridge plug at 37001 on Perforating Guns wire line. Dumped 501 cement on bridge plug.

7-23-53 Ferforated with Perforating Guns jet shots - 4 shots per foot from 3305-3345 and 3380 - 34301, 360 shots. Sweet hookwall packer set at 3286.921. Swabbed well in.

Tested through 2" tubing at rate of 5790 Mcf gas per day. Completed as gas well.

Witnessed by A 2 (Name) Humble 01	(Company) Company Farm Bose (Title)
Approved: OIL CONSERVATION COMMISSION	I hereby certify that the information given above is true and complete to the best of my knowledge.
A. Atar, lus	Name
(Name)	Position District Superintendent
1 19 53	Representing Humble Uil & Refining Compting

(Date)

Address Box 2347, Hobbs, N. H.

7-7-53 Hobbs, Nev Mexico

(Place)