STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

The same of the sa		
NO. 27 COPIES RECEIVED	7	
DISTRIBUTION	1	1
SANTA FE	1	
FILE	-	
U.S.G.S.	1	
LAND OFFICE	1	
OPERATOR		

HO, OF COPIES RECEIVED	OIL CONSERVATION DIVISION		
DISTRIBUTION	P. O. BOX 2088	•	
SANTA FE	SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-	
FILE			
U.S.G.S.		5a. Indicate Type of Lease	
OPERATOR .		State XX	
		5. State Oil & Gas Lease No.	
SUN NOT MENT SEN TON OO)	DRY NOTICES AND REPORTS ON WELLS PROFOSALS TO UNILL OR TO DEEPEN OF PUND DACK TO A DIFFERENT HESERVOIR. CATION FOR PERMIT - " FORM C-1011 FOR SUCH PROPOSALS."		
OIL GAS	- COACC)	7. Unit Agreement Name	
2. Name of Operator	OTHER-	Eunice Monument South Ut	
Chevron U.S.A.	Inc.	8. Farm or Lease Name	
3. Address of Operator			
P.O. Box 670, H	P.O. Box 670, Hobbs, NM 88240		
4. Location of Well		159	
1000		10. Field and Pool, or Wildcat	
CHILD	UNIT LETTER I 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM		
		Eunice Monument C/SA	
THE EAST LINE, SEC	TION 31 TOWNSHIP 20S RANGE 37E NMP	~ {	
	15. Elevation (Show whether DF, RT, GR, etc.)		
	3540'	12. County	
Check		Lea	
NOTICE OF	Appropriate Box To Indicate Nature of Notice, Report or C	ther Dara	
	SUBSEQUE	NT REPORT OF:	
PERFORM REMEDIAL WORK		·	
TEMPORATILY ABANDON	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
	CHANGE PLANS CASING TEST AND CEMENT JOB	THE AREA SEAMENT	
OTHER	OTHER Perf and acdz.		
		L	
7. Describe Proposed or Completed C	Operations (Clearly state all pertinent details, and give pertinent dates, includin		
Work) SEE RULE 1103.	state are pertinent details, and give pertinent dates, includin	g estimated date of starting any proposed	
		The any proposed	
POH w/rods	and pmp. Perf open hole w/ 4" guns, 1 JHPF, at :	2610 2600 2640	
3652-3664,	3677- 3680 and 3684-3700 (zones 1 & 2). Acidize	3612-3622, 3640-3644,	
15% NEFE HO	The Swah RIH perf open hale 2720 571 2701 27	W/3/00 gallons	
(186 holes)	CL. Swab. RIH perf open hole 3736-57', 3761-87	' , 3793–3839	
clean Aci). Break circ. w/ air foam. Clean out 3850- 3868	3 and blow hole	
CICUII. ACI	rdize open note W/3/00 gallons 15% NFFF HCL and 29	300 1ha CDC	
TIN W/ Prod	idection equipment and 2 //8 prod. the est top of	tha 3821	
1631 10 300	ppsi, ok. Turn over to production. Work performe	ed 9-1-87	
through 9–7	7-87.	- ·	
•		•	
I hereby certify that the information	above is true and complete to the best of my knowledge and belief.		
	complete to the best of my knowledge and belief.		
M. E. ah	, , , , , , , , , , , , , , , , , , ,		
	Your Staff Drilling Engineer	C . 1 . 0 . 100-	