DISTRICT I SUPERVISOR	MAR 1 1 1987
ORIGINAL SIGNED BY JERRY SEXTON	3-9-87
, M. E. Whim Staff Drilling Engineer	2.0.17
nereby certify that the information above is true and complete to the best of my knowledge and belief.	
	•
•	
Clean out to TD @ 3840 . Log well. Add additional Grayburg peindicate. Acidize as necessary. Equip for injection. Test casing, 600 psi. for 30 minutes. Return to production as an injector.	rrorations as logs packer, and tubing to
Clean out to TD @ <u>3840</u> . Log well. Add additional Grayburg pe	
work) SEE RULE 1103.	estimated date of starting any proposed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including pork) SEZ RULE 1103.	
CONVERT TO INJECTOR	·
OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
PORARILY ABANDON PLUC AND ABANDON REMEDIAL WORK	ALTERING CASING
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
15. Elevation (Show whether DF, RT, GR, etc.) 3541 GL	LEA
THE West LINE. SECTION 32 TOWNSHIP 20S RANCE 37E	
WHIT LETTER K 1980 FEET FROM THE SOUTH LINE AND FEET FROM	EUNICE MONUMENT G/SA
P.O. Box 670 Hobbs, NM 88240	156
dress of Operator	9. Well No.
Chevron U.S.A. Inc.	EUNICE MONUMENT SOUTH UN
OTHER-INJECTOR	7. Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS  100 HOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUE BACK TO A DIFFERENT RESERVOIR.  100 HOT USE THIS FORM FOR PROPOSALS.)	
	5. State Ott & Gas Lease No.
LAND OFFICE	State X Fee
U.S. d.S.	Sa. Indicate Type of Lease
SANTA FE SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-78
C _ CONSERVATION DIVISION	•
THIS CAND MINERALS DEPARTMENT	