## OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

XXXX 1980

Sept. 24, 1964

Harper d Company 904 Higtower Bldg. Oklahom City, Okla.

Gentleen:

A packr leakage retest on your Sarkeys No. 1 located in Unit G of Sec. 28, T-1-S, R-37-E indicated communication and this office directed you to regir this communication by letter dated July 6, 1964. To date nothig has been received in this office to indicate that the repairs have ben made or that work has commenced on this well.

Since communication is known to exist in this well bore, it will be necessary that the well be shut in until the communication is repaired. I am therefore notifying your transporters that the allowable for both sone, in this well has been cancelled. When the communication has been repaired and a new packer leakage test for the well has been filed, the allowables will be reinstated.

Yours very truly,

OIL CONSERVATION COMMISSION

Joe D. Ramey Supervisor, District 1

JR/mc

# OIL CONSERVATION COMMISSION

#### HOBBS, NEW MEXICO

CAX 1930

### 38pt. 24. 55%

darjarik, "Gapanj. 900 Hittower Blog. 9 Jahr Sirk, Skua.

ങ്ങിടങ്ങി

A packr leakage releat on your farkeys He. I located in Unit H of Ser. 25, TL-5, 2-37-b indicated communication and this office directed you to reare this communication by letter dated July 6, 1961. To date nothig has been received in this office to indicate that the repairs have sen made or that work has commenced on this welt.

Since communication is known to exist in this well here, it will be necessary that the well be shut in until the commutation is approxibasthere notifying your mansporters that the allowable for both stand in this well has been cancelled. When the commutation has been repaired and a new packer leakage test for the well has been filed, one all shires will be reinstates.

YOU'S VERY DEBLY,

### VOISEEMNOO NOTTAVHISMOS LEE

dee 1. Susey Soperviser, Siscrict I

101 M 2