	RECEIVED	• • ··
DUPLICATE	OIL CONSERVATION COMMISSION Santa Fe, New Mexico APR 1 6 1951	04
	-REQUEST FOR (OIL)-(GAS) ALLOWABLOU CONSERVATION COMMISSION	
It is necessary that this	s form be submitted by the operator before an initial allowable	
will be assigned to any	completed oil or gas well. Form C-110 (Certificate of Comple	
ance and Authorization to	O Transport (11) will not be approved until Form C. 104 to filed	
with the commission. For	rm U-104 is to be submitted in trinlicate to the office to which	
Form C-101 was sent. Two	o copies will be retained there and the other submitted to the	
on date of completion m	New Mexico. The allowable will be assigned effective 7:00 a.m.	
The completion date shall	rovided completion report is filed during month of completion. I be that date in the case of an oil well when oil is delivered	
into the stock tanks. Ge	as must be reported on 15.025 P.B. at 60° Fahrenheit.	
Hobbs, New Mexico	Ap r11 13, 1951 Date	
1 40	Date	
WE ARE HEREBY REQUESTING	AN ALLOWABLE FOR A WELL KNOWN AS:	
Continental Off Company	Lockhart A-27 Well No. LeE in SE 1/4 NW 1/4	
section 27, T. 215,	R. 37E N.M.P.M. Brunson Pool Loa County	
Please indicate location:	Elevation 3417 Supported 3-5-51 Completed 4-6-51	
	Total Depth 7541 P.B. 7530	
	Top Oil/Gas Pay 7390 Top Water Pay	
	Initial Production Test: PumpFlow 702 (BOPD OR CU.FT)	
x	Based on <u>351</u> Bbls. 011 in <u>12</u> Hrs. Mins.	
*	Method of Test (Pitot, gauge, prover, meter run): Gauge	
	Size of choke in inches	
	Tubing (Size) 21/2" @ 7478 Feet	
	Pressures: Tubing 50# Casing 0 - Packer	
	Pressures:Tubing50#Casing0 - PackerGas/0il Ratio1513Gravity46.5	
	Pressures: Tubing <u>50</u> Casing <u>0 - Packer</u> Gas/0il Ratio <u>1513</u> Gravity <u>46.5</u> Casing Perforations:	
Unit letter:	Pressures: Tubing <u>50</u> Casing <u>0 - Packer</u> Gas/011 Ratio <u>1513</u> Gravity <u>46.5</u> Casing Perforations: 7452-7474; 7462-7491; 7499-7506; 7514-7526; Total 200 holes,	
Unit letter:	Pressures: Tubing <u>50</u> Casing <u>0 - Packer</u> Gas/0il Ratio <u>1513</u> Gravity <u>46.5</u> Casing Perforations:	
Unit letter: F Casing & Cementing Record	Pressures: Tubing 50# Casing O = Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452=7474*; 7482=7491*; 7499=7506*; 7514=7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water 500 Gals 7452 to 7526 S/	
	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 74.52=74.74.*; 74.62=74.91*; 74.99=7506*; 7514=7526*. Total 200 holes, Acid Record: Show of 0il, Gas and water	
Casing & Cementing Record Size Feet Sax	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452-7474*; 7482-7491*; 7499-7506*; 7514-7526*. Total 200 holes, Acid Record: Show of 0il,Gas and water	
Casing & Cementing Record	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452-7474*; 7482-7491*; 7499-7506*; 7514-7526*. Total 200 holes. Acid Record: Show of 0il,Gas and water	
Casing & Cementing Record Size Feet Sax 12 3/4 226 200	Pressures: Tubing 50# Casing 0 - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452=7474*; 7482=7491*; 7499=7506*; 7514=7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water 500 Gals 7452 Gals to S/	
Casing & Cementing Record Size Feet Sax	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 74.52=74.74*; 74.82=74.91*; 74.99=7506*; 7514=7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water	
Casing & Cementing Record Size Feet Sax 12 3/4 226 200 9 5/8 2425 500	Pressures: Tubing 50# Casing 0 - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 74.52=74.74*; 74.82=74.91*; 74.99=7506*; 7514=7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> 9 5/8 2425 500 7 6572 500	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 74.52=74.74.*; 74.82=74.91*; 74.99=7506*; 7514=7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liper 1095</u>	Pressures: Tubing 50# Casing 0 - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 74.52-74.74*; 74.82-74.91*; 74.99-7506*; 7514-7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liner 1095</u> <u>6445 to 7540* 140</u>	Pressures: Tubing 50# Casing O = Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 74.52=74.74.*; 74.62=74.91*; 74.99=7506*; 7514=7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water 500 Gals 74.52 to 7526 S/	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liner 1095</u> <u>6445 to 7540* 140</u>	Pressures: Tubing 50# Casing 0 - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 74.52-74.74.*; 74.62-74.91*; 74.99-7506*; 7514-7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water 500 Gals 74.52 to 7526 S/	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liner 1095</u> <u>6445 to 7540</u> <u>140</u> Please indicate below Form	Pressures: Tubing 50# Casing 0 - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452-7474.*; 7482-7491*; 7499-7506*; 7514-7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liner 1095</u> <u>6445 to 7540* 140</u> Please indicate below Form Southeaste	Pressures: Tubing 50# Casing O = Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452=7474*; 7482=7491*; 7499=7506*; 7514=7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Limer 1095</u> <u>6445</u> to 7540° 140 Please indicate below Form Southeaster T. Anhy	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452-7474*; 7482-7491*; 7499-7506*; 7514-7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liner 1095</u> <u>6445 to 7540! 140</u> Please indicate below Form Southeaster T. Anhy T. Salt	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452=7474*; 7482=7491*; 7499=7506*; 7514=7526*. Total 200 holes. Acid Record: Show of 011, Gas and water 500 Gals 7452 Gals to 7526 Gals 7452 Gals to Show of 011, Gas and water 500 Gals Gals to Gals to Shooting Record. S/	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liner 1095</u> <u>6445 to 7540</u> 140 Please indicate below Form Southeaster T. Anhy T. Salt B. Salt	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452=7474*; 7482=7491*; 7499=7506*; 7514=7526*. Totel 200 holes. Acid Record: Show of 011,Gas and water	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liner 1095</u> <u>6445</u> to 7540* 140 Please indicate below Form Southeaste T. Anhy T. Salt B. Salt T. Yates	Pressures: Tubing 50# Casing 0 - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452-74.74*; 74.62-74.91*; 74.99-7506*; 7514-7526*. Total 200 holes. Acid Record: Show of 011,Gas and water	
Casing & Cementing Record <u>Size Feet Sax</u> <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liner 1095</u> <u>6445 to 7540</u> 140 Please indicate below Form Southeaster T. Anhy T. Salt B. Salt	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452-74.74*; 74.82-74.91*; 74.99-7506*; 7514-7526*. Total 200 holes. Acid Record: Show of 0il, Gas and water	
Casing & Cementing Record <u>Size</u> Feet Sax <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liner 1095</u> <u>6445 to 7540! 140</u> Please indicate below Form Southeaste T. Anhy T. Salt B. Salt T. Yates T. 7 Rivers T. Queen T. Grayburg	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452-7474'; 7462-7491'; 7499-7506'; 7514-7526'. Total 200 inoles. Acid Record: Show of 0il,Gas and water	
Casing & Cementing Record <u>Size</u> Feet Sax <u>12 3/4 226 200</u> <u>9 5/8 2425 500</u> <u>7 6572 500</u> <u>5"Liner 1095</u> <u>6445 to 7540</u> 140 Please indicate below Form Southeaste T. Anhy T. Salt B. Salt T. Yates T. 7 Rivers T. Queen T. Grayburg T. San Andres	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452=74.74.*; 74.82=74.91*; 74.99=7506*; 7514=7526*. Total 200 holes. Acid Record: Show of 011, Gas and water	
Casing & Cementing Record Size Feet Sax 12 3/4 226 200 9 5/8 2425 500 7 6572 500 5"Liner 1095 6445 to 7540* 6445 to 7540* 140 Please indicate below Form Southeaste T. Anhy	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452=7474/1; 7482=7491; 7499=75061; 7514=75261. Total 200 holes. Acid Record: Show of 011, Gas and water 500 Gals 7452 Gals to S/	
Casing & Cementing Record Size Feet Sax 12 3/4 226 200 9 5/8 2425 500 7 6572 500 5"Liner 1095 6445 to 7540* 140 Please indicate below Form Southeaster T. Anhy	Pressures: Tubing 50# Casing 0 - Packor Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452=7474/1; 7452=74911; 7499=75061; 7514=75261. Total 200 holes. Acid Record: Show of 011, Gas and water	
Casing & Cementing Record Size Feet Sax 12 3/4 226 200 9 5/8 2425 500 7 6572 500 5"Liner 1095 6445 to 7540* 6445 to 7540* 140 Please indicate below Form Southeaste T. Anhy	Pressures: Tubing 50# Casing 0 - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 74.52=74.74.*; 74.82=74.91 *; 74.99=7506 *; 7514=7526 *. Total 200 holes. Acid Record: Show of 0il, Gas and water	
Casing & Cementing Record Size Feet Sax 12 3/4 226 200 9 5/8 2425 500 7 6572 500 5"Liner 1095 6445 to 7540* 6445 to 7540* 140 Please indicate below Form Southeaster T. Anhy	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452-7474'; 7482-7491'; 7499-7506'; 7514-7526'. Total 200 holes. Acid Record: Show of 011,Gas and water	
Casing & Cementing Record Size Feet Sax 12 3/4 226 200 9 5/8 2425 500 7 6572 500 5 ⁿ Limer 1095 6445 to 7540 ^a 6445 to 7540 ^a 140 Please indicate below Form Southeaste T. Anhy	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452-7474'; 7452-7491'; 7499-7506'; 7514-7526'. Total 200 holes. Acid Record: Show of 0il,Gas and water	
Casing & Cementing Record Size Feet Sax 12 3/4 226 200 9 5/8 2425 500 7 6572 500 5"Liner 1095 6445 to 7540* 140 Please indicate below Form Southeaster T. Anhy	Pressures: Tubing 50# Casing O - Packer Gas/011 Ratio 1513 Gravity 46.5 Casing Perforations: 7452-7474'; 7482-7491'; 7499-7506'; 7514-7526'. Total 200 holes. Acid Record: Show of 011,Gas and water	

(Please supply required information on reverse side of form)

Date first oil run to tanks or gas to pipe line: <u>4-6-51</u> Pipe line taking oil or gas: <u>Texas-New Mexico Fipe Line Company</u> Remarks: <u>Originally designated as Lockhart 1-27 No. 3. Spudded 6-1-67</u> and completed as dry hole in Drinkard and temporarily abandoned 9-28-47. Workover started 1-10-50 in attempt to complete as Tubb gas well, completed as dry hole and temporarily abandoned from 1-18-50 until 4-5-51 when workover to #

Continental Oil Company Company or Operator h. Shap

Position: District Superintendent

Send communications regarding well to:

Name: _____Continental Cil Coupany Address: Box CC, Hobbs, New Nextco

APPROVED 4 ~ 16 . 1951 OIL CONSERVATION COMMISSION

*despen and complete as Ellenburger was begun. After workover completed and production from Ellenburger established on 4-12-51, well was redesignated as Lockhart A-27 No. 4-E.