

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate  
(Other instruction  
verse side)

Budget Bureau NO. 1004-0133  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR  
**CONOCO INC.**

3. ADDRESS OF OPERATOR  
**P. O. Box 460, Hobbs, N.M. 88240**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface **Unit D**

14. PERMIT NO.  
**810' FNL & 660' FWL**

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
**30-025-06805**

5. LEASE DESIGNATION AND SERIAL NO.

**LC-032096(A)**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

**Lockhart A-27**

9. WELL NO.

**8**

10. FIELD AND POOL, OR WILDCAT

**Blinberry Oil & Gas/Drinkwater**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

**Sec. 27-215-37E**

12. COUNTY OR PARISH

**Lea**

13. STATE

**NM**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

**recomplete to Paddock**

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- ① MIRU. POOH w/ tbg & pkr. Tag PBTB @ 6505. Dump 7sxs cmt on CIBP @ 6505. 6472'. Set CIBP @ 6350'. Dump 8sxs cmt on top of CIBP @ 6350.
- ② Set CIBP @ 5480'. Dump 8sxs cmt on top of CIBP @ 5480'. GIH w/ 6R tool and log from 5400'-4900'. Spot 2 bbls 15% HCL-NE-FE from 5265-5214'. GIH and perf from 5250'-5265' w/ 4 JS PF.
- ③ Set RBP @ 5350' and pkr @ 5150'. Acidize perms w/ 32 bbls 15% HCL-NE-FE and flush w/ 36 bbls 2% KCL TFW + 1 gal Adomall per 1000 gals. Swab.
- ④ Rel RBP & pkr & POOH. Spot 3 bbls 15% HCL-NE-FE from 5180'-5105'. GIH & perf from 5155'-65' 5175'-80' 5185'-90' w/ 4 JS PF. Set pkr @ 5055' and RBP @ 5230'. Acidize upper Paddock perms w/ 70 bbls 15% HCL-NE-FE and flush w/ 34 bbls 2% KCL TFW + 1 gal Adomall per 1000 gals. Swab.
- ⑤ Release pkr @ 5055' & RBP @ 5230'. Hang well on & rig down

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE **Administrative Supervisor**

DATE **8-6-86**

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE **8/26/86**

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carl (3) bad (6) ARCO (2) AMOCO (2) Chevron (1) File