

NEW MEXICO OIL CONSERVATION COMMISSIO

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until commission

Notice of Intention	Indicate Nature of Notice by Checki	ng Below	
TO CHANGE PLANS	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Notice of Intention to Plug Back	Notice of Intention to Set Liner	
Notice of Intention to Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	Notice of Intention (Other)	Notice of Intention (Other)	
OIL CONSERVATION COMMISSI SANTA FE, NEW MEXICO	Hobbs, New Nextco	1-13-53 (Date)	,
Gentlemen:			
Following is a Notice of Intention	on to do certain work as described below at the	F. F. Hardison B	
Humble 011 & Refini	ing Company Operator) 27 219 272	Well No. 8	1
NE	27 , T. 218 , R 378 ,NA	OM Drinkard	(Unit)
procedure: 1) Rig up. k	FULL DETAILS OF PROPOSED PLA LLOW INSTRUCTIONS IN THE RULES A is proposed to acid treat the ill wall and pull 2-1/2-inch to	ND REGULATIONS) Well ascording to the form	
precedure: 1) Rig up, k with Lene Wells Heckwall jel and 5,000 gallons of	LLOW INSTRUCTIONS IN THE RULES AS is proposed to acid treat the ill well and pull 2-1/2-inch twill parker, 3) directate with cill I lew tension acid. A) systematically statements and all systems and all systems.	ND REGULATIONS) well ascording to the fe bing, 2) rerun 2-1/2-in	taking
precedure: 1) Rig up, k with Leme Wells Heckwall jel and 5,000 gallons of	LLOW INSTRUCTIONS IN THE RULES AS is proposed to acid treat the ill well and pull 2-1/2-inch twill parker, 3) directate with cill I lew tension acid. A) systematically statements and all systems and all systems.	ND REGULATIONS) well ascording to the fe bing, 2) rerun 2-1/2-in	taking
precedure: 1) Rig up, k with Leme Wells Hechwall jel and 5,000 gallons ex down and place well on	LLOW INSTRUCTIONS IN THE RULES AS is proposed to acid treat the ill wall and pull 2-1/2-inch twill packer, 3) directate with cill lew tension acid, 4) swab out production. By	well ascording to the folding, 2) rerun 2-1/2-ine, and treat with 1,000 gracid load and test, 5) le Oil & Refining Company of Operator Company of Operator	ch tubing milens of tear
precedure: 1) Rig up, k with Leme Wells Hookwali jel and 5,000 galloms en down and place well on	is proposed to acid treat the ill well and pull 2-1/2-inch twill pasker, 3) directate with cill lew tension acid, 4) swab out production. By	well ascording to the folding, 2) rerum 2-1/2-inding, 2 rerum 2-1/2-inding, and treat with 1,000 gracid load and test, 5)	th tubing