

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-06815
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: J. N. CARSON (NCT-A)
8. Well No. 8
9. Pool name or Wildcat PADDOCK
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other
2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator P.O. Box 1150 Midland, TX 79702
4. Well Location Unit Letter O : 766 feet from the SOUTH line and 2086 feet from the EAST line Section 28 Township 21S Range 37E NMPM County LEA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PUL. OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	

OTHER: ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

POH W/PROD EQPT. SET CIBP @ 5000', TAGGED. SPOT 25 SX CMT, TAGGED @ 4860'. PERFD 2851' W/4 JHPF. REPAIRED LEAK IN CELLAR. CIRC HOLE CLEAN. SET CIRC @ 2750'. PPD 500 SX CMT; CIRC TO SURF. DUMPED CMT ON CIRC. TAGGED PLUG @ 2592'. PPD 25 SX CMT 2450'-2301'. PPD 45 SX CMT 1318'-1050'. PERFD 250'-354' W/4 JHPF. FILLED 7" CSG W/CMT. PPD 130 SX CMT UP 13-3/8" AND IN CELLAR. SET MARKER, CLEANED LOCATION.

P&A'D 8/28/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE REGULATORY O.A. DATE 9/25/01
Type or print name J. K. RIPLEY Telephone No. (915)687-7148

(This space for State use)
APPROVED BY [Signature] TITLE State Rep DATE 2-12-03
Conditions of approval, if any:

GWW