

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Chevron U.S.A. Inc. 3. Address of Operator P.O. Box 670, Hobbs, NM 88240 4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 2180 FEET FROM THE East LINE, SECTION 28 TOWNSHIP 21S RANGE 37E WPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3442' GL	7. Unit Agreement Name 8. Farm or Lease Name J. N. CARSON (NCT A) 9. Well No. #10 10. Field and Pool, or Wildcat Hare Simpson 12. County Lea
--	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to POH w/ PE, tag for fill before POH. If fill is present, clean out with a small bailer. RIH w/ wireline bailer and dump 20/40 mesh sand from PBTD at 7425' to 7323', (10' below top of 4" liner). Dump 20' of 12/20 resin-coated sand on top of the 20/40 sand up to 7303', Apply activator as necessary to bond sand. POH. RIH w/PE (no screens) and land BPMA one joint above top of sand. RDMOPU. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. E. Akins TITLE STAFF DRILLING ENGINEER DATE JUNE 18, 1987

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 23 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 22 1961
OCE
GROUPS OFFICE

100-100000