

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name J. N. Carson (NCT-C)
3. Address of Operator Box 670, Hobbs, New Mexico 88240		9. Well No. 7
4. Location of Well UNIT LETTER P , 554 FEET FROM THE South LINE AND 554 FEET FROM THE East LINE, SECTION 28 TOWNSHIP 21-S RANGE 37-E NMPM.		10. Field and Pool, or Whicout Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3439' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Perforate additional zone & acidize <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

5300' PB.

Pull producing equipment. Perforate 7" casing in Paddock zone with 2, 1/2" JHPF at 5244-54'. Treat new perforations with 2500 gallons of 15% NE acid. Swab and clean up and return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. J. Brazeele TITLE Area Engineer DATE April 6, 1971

APPROVED BY _____ TITLE _____ DATE _____

AND OPNS OF APPROVAL, IF ANY: