

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Chevron USA, Inc.	6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd. Midland, TX 79705	7. Lease Name or Unit Agreement Name: Central Drinkard Unit
4. Well Location Unit Letter <u>I</u> : 1980 feet from the <u>south</u> line and <u>990</u> feet from the <u>east</u> line Section <u>28</u> Township <u>21-S</u> Range <u>37-E</u> NMPM County <u>Lea</u>	8. Well No. 100
9. Pool name or Wildcat	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. **Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hrs prior to MI & RU
2. RIH set 7" CIBP @ 4000', spot 20sx plug 4000'-3900'(San Andres) WOC Tag.
3. Displace hole w/MLF, 9.5# Brine w/25# Gel p/BBL.
4. Spot 40sx plug 3600'-3400'(Queen)
5. Perf 4 holes @ 2800', sqz 75sx plug 2800'-2600'(9 5/8 shoe, T-salt) WOC Tag.
6. Perf 4 holes @ 1400', sqz 75sx plug 1400'-1200'(T-salt)
7. Perf 4 holes @ 350',sqz 75sx plug 350'-150'(13 3/8 shoe) WOC Tag
8. 10 sx surf, Install dry hole marker.

THIS FORM IS TO BE COMPLETED 24
HOURS PRIOR TO THE STARTING OF
ANY WORK. INFORMATION FOR THE C-103
IS TO BE REVIEWED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G.R. Bledsoe TITLE HES Specialist DATE 10/7/2002

Type or print name G.R. Bledsoe Telephone No. 915.687.7153
(This space for State use)

APPROVED BY _____ TITLE ORIGINAL SIGNED BY
Conditions of approval, if any: PAUL F. KAUTZ DATE OCT 08 2002
PETROLEUM ENGINEER

PLUGGING & ABANDONMENT WORKSHEET

(3 STRING CSNG)

OPERATOR CHEVR USA INC.

LEASE NAME CENTRAL DEINKARD UNIT

WELL # 100

SECT 28

TWN 21-S

RNG 31-E

FROM 1980

N5L 990

EWL

TD 7743

FORMATION @ TD BRUNSON -

PBTD 4870

FORMATION @ PBTD SAN- ANDRES

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	13 3/8	300	SURF	Circ
INTMED 1	9 5/8	2800	1275	T.S.
INTMED 2				
PROD	7"	7374	2800	T.S.

	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1	5 1/2	7325	7743	7325	Circ.
LINER 2					

	CUT & PULL	TOP - BOTTOM
INTMED 1	PERFS	4055-4795
INTMED 2	OPENHOLE	
PROD		

*REQUIRED PLUGS DISTRICT

	PLUG	TYPE PLUG	SACKS CEMENT	DEPTH
RUSTLER (ANHYD)	1	CIBP	20	4000'
YATES	2	QUEEN	40	3600
QUEEN	3	9 5/8 S	75	2800
GRAYBURG	4	T-SALT	75	1400
SAN ANDRES	5	13 3/8 S	75	350
CAPITAN REEF	6	SURF	10	10
DELAWARE				
BELL CANYON				
CHERRY CANYON				
BRUSHY CANYON				
BONE SPRING				
GLORIETA				
BLINBRY				
TUBB				
DRINKARD				
ABO				
WC				
PENN				
STRAWN				
ATOKA				
MORROW				
MISS				
DEVONIAN				

MLF

13 3/8

@ 300

TOC SURF

MLF

9 5/8

@ 2800

TOC 1275

MLF

7"

@ 7374

TOC 2800

MLF

5 1/2 LINER

@ 7325-7743

TOC 7325

TD 7743