

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

APR 1 PM 3 42

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK & Recomp. in Bl.		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Hebbs, New Mexico
(Place)

April 1, 1963
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Gulf Oil Corporation J. N. Carson (NCT-C) Well No. 8 in I
(Company or Operator) (Unit)
NE 1/4 SE 1/4 of Sec. 28, T. 21-S, R. 37-E, NMPM, Brunson and Blinbry Pool
(40-acre Subdivision)
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

PBTD 7741'.

It is proposed to abandon Brunson and recomplete in Blinbry as follows:

1. Pull rods, pump and tubing.
2. Set CI BP at approximately 7300' with wire line and dump 2 sacks of cement on top of BP. Test with 1000#.
3. Run GR-N log from PBTD to 3000' on 2" scale and from PBTD to 5000' and 4000' to 3000' on 5" scale.
4. Selectively perforate Blinbry zone.
5. Run 4-1/2" tubing with retrievable B.P. and FB packer. Spot 500 gallons of 15% NEA over perforations and squeeze into formation. After squeezing acid, set packer and frac treat with 32,000 gallons of gelled lease oil containing 1/20# PG of Silica flour.
6. Pull frac tubing. Run 2-3/8" tubing and place well on production

Approved....., 19.....
Except as follows:

Approved
OIL CONSERVATION COMMISSION

By.....
Title.....

Gulf Oil Corporation
Company or Operator

By.....

Position..... Area Production Manager
Send Communications regarding well to:

Name..... Gulf Oil Corporation

Address..... Box 2167, Hebbs, New Mexico