

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

Form C-103
Revised 1-1-89

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer Dd, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-06838	
6. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name EUNICE KING	
8. Well No. 2 SWD	
8. Pool name or Wildcat PENROSE SKELLY <i>See Address</i>	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER DISPOSAL	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>28</u> Township <u>21 SOUTH</u> Range <u>37E</u> NMPM LEA County	
10. Elevation(Show whether DF, RKB, RT, GA, etc.) 3472' GL	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including anticipated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO PLUG AND ABANDON THIS WELL AS FOLLOWS:
SET CICR AT 3557'. SQZ OH BELOW CICR WITH 150 SX CMT, SET 35' CMT (5 SX) ON TOP.
SET 400' PLUG FROM 2400' TO 2000', 68 SX CMT.
SET 300' PLUG FROM 1300' TO 1000', 51 SX CMT.
SET 300' PLUG FROM 500' TO 200', 51 SX CMT.
SET 100' PLUG FROM 100' TO SURFACE, 17 SX CMT.
ALL PLUGS ARE CLASS C NEAT MIXED AT 14.8 PPG, 1.32 CU/FT SX. DISPLACE HOLE WITH 9.5 PPG MUD LADEN FLUID.
PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION, PLACE P&A MARKER AND CHANGE STATUS OF WELL TO PLUGGED AND ABANDONED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <i>Wendi Kingston</i>	TITLE TECH. ASSISTANT	DATE: 03/17/94
TYPE OR PRINT NAME WENDI KINGSTON		TELEPHONE NO. (915)687-7436

APPROVED BY	TITLE	DATE
Orig. Signed by Paul Kautz	Geologist	MAR 1994

CONDITIONS OF APPROVAL, IF ANY:

THIS FORM IS A PART OF THE RECORD OF THE OIL CONSERVATION DIVISION AND IS TO BE KEPT IN THE FILES OF THE OIL CONSERVATION DIVISION.