

Submit 3 Copies
to Appropriate
District Office

2

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

Form C-103
Revised 1-1-89

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)	30-025-06847
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	N/A
7. Lease Name or Unit Agreement Name	CENTRAL DRINKARD UNIT
8. Well No.	102
9. Pool name or Wildcat	DRINKARD
10. Elevation(Show whether DF, RKB, RT, GR, etc.)	3457' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
CHEVRON U.S.A. INC.

3. Address of Operator
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

4. Well Location
Unit Letter B : 554 Feet From The NORTH Line and 2086 Feet From The EAST Line
Section 28 Township 21S Range 37E NMPM LEA County

10. Elevation(Show whether DF, RKB, RT, GR, etc.)
3457' GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☒
CASING TEST AND CMT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 1-17 THRU 1-21-94
PLUG #1, SET CIBP @ 6490', W/25 SX PLUG 6490-6341.
PLUG #2, 35 SX CMT F/5134-4925' (COVERS GLORIETTA)
PLUG #3, PERF @ 2850, PMP 60 SX INTO PERFS & LEAVE 50' CMT IN 7" CSG.
TAG TOC @ 2780', CIRC P&A MUD. SPOT 35 SX CMT 1260-1051'
PERF @ 350', PMP DN CSG & CIRC UP SURFACE & INTERMEDIATE CSG.
SET CIRC @ 252, PMP 190 SX CMT. CIRC UP SURFACE & INT CSG.
DUMP 10 SSX ON CIRC. SPOT 10 SX CMT SURFACE PLUG.(9.5 PPG MUD BETWEEN ALL PLUGS)
PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION, PLACE P&A MARKER
CHANGE STATUS OF WELL TO PLUGGED AND ABANDONED.
OCD REP CHARLIE PERRIN ON LOCATION & OK'D ALL PLUGS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice

TITLE TECHNICAL ASSISTANT

DATE: 2/10/94

TYPE OR PRINT NAME NITA RICE

TELEPHONE NO. (915)687-7436

APPROVED BY

Charlie Perrin

TITLE OCD REP

DATE

APR 08 1994

CONDITIONS OF APPROVAL, IF ANY: