ENERGY AND MINERALS DEPARTMENT	
OIL CONSERVATION DIVIS: N	*
1 1 3	
7. O. BOX 2088	Form C-103 Revised 10-1-
SANTA FE, NEW MEXICO 87501	
U.\$.a.\$.	Sa. Indicate Type of Leuse
LAND OFFICE	State . Fee X
DPENATOR	5. State Oil & Cas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" IFCAM C-1011 FOR SUCH PROPOSALS.)	
OIL 🕅 6A3 🗍	7. Unit Agreement Name
WELL A WELL OTHER.	· ·
2. Name of Operator	8. Fam of Lease Name
Gulf Oil Corporation	Eunice King
3. Address of Cherator	9. West No.
P. O. Box 670, Hobbs, NM 88240	22
Location of well	10. Field and Pool, or Whideat
UNIT LETTED B . 554 FEET FROM THE NORTH LINE AND 1874 FEET FROM	
FEET PROM	Hare Simpson
THE East LINE, SECTION 28 TOWNSHIP 21S RANGE 37E HMPM.	
THE 1300 LINE, SECTION 20 TOWNSHIP 215 RANGE 3/E HMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
3454' GL	12. County
	Lea (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ADAHDON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMENT JOB	
other Cleaned Out	X
OTHER	
7. Describe Emposed of Completed Oversitons (Clarks and III)	• .
7. Describe Francised or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of starting any propose
POH with production agreement of	
POH with production equipment. Clean out with sand pump to 7650'.	GIH with produc-
tion equipment. Restore well to pumping in test; well failed to pu Well status report will follow.	mp up (well parted).
well beachs leport will lollow.	
	•
	•
•	